

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 11.05.2022

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBJ4293T**
MODEL : **TOYOTA DYNA**
DATE OF ACCIDENT : 08.05.22
TIME OF ACCIDENT : 10:30HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT FUSE BOX <i>Good</i>	1	\$ 280.00	\$ 280.00
2	FRONT FUSE BOX BRACKET <i>He on</i>	1	\$ 95.00	\$ 95.00
3	FRONT WHEEL REAR MUDGUARD LH <i>Behind</i>	1	\$ 186.70	\$ 186.70
4	FRONT WHEEL REAR MUDGUARD LOWER BRACKET LH <i>3M</i>	1	\$ 85.00	\$ 85.00
5	FRONT WHEEL REAR MUDGUARD UPPER BRACKET LH <i>3M</i>	1	\$ 80.00	\$ 80.00
6	REAR SIDE GATE LH <i>Dented</i>	1	\$ 1,778.90	\$ 1,778.90
7	REAR SIDE GATE HINGE LH <i>Dented 2 pieces</i>	3	\$ 95.90	\$ 287.70 197.80
8	REAR SIDE GATE STOPPER LH <i>new</i>	1	\$ 24.60	\$ 24.60
9	REAR CARGO BED SIDE FRAME LH <i>Repair</i>	1	\$ 1,576.20	\$ 1,576.20
10	REAR WHEEL FRONT FENDER LH <i>Distorted</i>	1	\$ 243.80	\$ 243.80
11	REAR WHEEL BACK FENDER LH <i>Repair</i>	1	\$ 239.90	\$ 239.90
12	REAR AXLE <i>2</i>	1	\$ 2,887.15	\$ 2,887.15
13	GEAR BOX GASKET	1	\$ 219.40	\$ 219.40
14	REAR WHEEL HUP SHAFT RH <i>1M</i>	1	\$ 874.40	\$ 874.40
15	REAR WHEEL HUP RH <i>new</i>	1	\$ 396.10	\$ 396.10
16	REAR WHEEL HUP BEARING RH	1	\$ 241.30	\$ 241.30
17	REAR WHEEL HUP OIL SEAL RH	1	\$ 74.60	\$ 74.60

2681.20 TOTAL PRICE \$ 9,570.75
2010.90 LESS 25% \$ 2,392.69
SUB TOTAL PRICE \$ 7,178.06

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT WHEEL TYRE RH <i>2</i>	1	\$ 350.00	\$ 350.00
2	REAR WHEEL TYRE RH <i>2</i>	1	\$ 280.00	\$ 280.00
3	BRAKE OIL <i>new</i>	1	\$ 40.00	\$ 40.00
4	GEAR OIL	1	\$ 180.00	\$ 180.00

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBJ4293T**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 08.05.22
 TIME OF ACCIDENT : 10:30HRS

5	BATTERY <i>He new</i>	1	\$ 250.00	\$ 250.00	<i>x.</i>
---	-----------------------	---	-----------	-----------	-----------

TOTAL \$ 1,100.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 1,200.00	<i>400.</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,000.00	<i>600</i>
3	TO SPRAY TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING, BULB CHECKING	\$ 80.00	<i>30</i>
5	TRANSFER SIDE GATE MECHANISM	\$ 80.00	<i>x.</i>
6	REMOVE AND REFIX RAILLING	\$ 150.00	<i>x</i>
7	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	<i>x</i>
8	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>x</i>
9	REMOVE AND REFIX REAR CANOPY	\$ 250.00	<i>x</i>
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>x</i>

TOTAL \$ 3,960.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,278.06
 TOTAL LABOUR COST : \$ 3,960.00
 TOTAL REPAIR COST : \$ 12,238.06

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

- the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Adrian Lj
 H/S 11/05/22.
 04 Days.*

*total: 3100.90
 C/S: 2.4K.*

1090