



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|-----------------|----------------------------|--|
| STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705 | | | Ref: CS/SMR22004372/Aqy3e2 | |
| | | | Date: 01/09/2022 | |
| | | | Code: SMR | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SHD 6313S | Veh. Inspected | SLG 9215J | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | TAX/05/22/2019 | Excess (\$) | 0.00 | |
| Assign From | ASHLENE LEE | Assign Date | 10/05/2022 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | MERCEDES BENZ C180 COUPE | c.c | 1595 | |
| Engine No. | HIDDEN | Year of Reg. | 2016 | |
| Chassis No. | WDD2053402F346668 | Colour | BLACK | |
| Odometer | 92391 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 245/40 R18 | GOODYEAR | 6 mm | |
| L/H Front Tyre | 245/40 R18 | GOODYEAR | 6 mm | |
| R/H Rear Tyre | 245/40 R18 | GOODYEAR | 6 mm | |
| L/H Rear Tyre | 245/40 R18 | GOODYEAR | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 09/05/2022 | Inspection Date | 10/05/2022 | |
| Survey held at | N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 4 Working Days | |