

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 4056R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	LEFT FRONT DOOR	DAMAGED	1,422.00	1,422.00
1	LEFT REAR DOOR	DAMAGED	1,422.00	1,166.00
1	LEFT FRONT DOOR LOWER GARNISH	SCRATCHED	365.00	365.00
1	LEFT REAR DOOR LOWER GARNISH	SCRATCHED	365.00	274.00
1	LEFT FRONT DOOR PW MOTOR	NOT NECESSARY	496.00	-
1	LEFT FRONT DOOR PW RACK	NOT NECESSARY	377.00	-
1	LEFT FRONT DOOR PW MOTOR SWITCH	NOT NECESSARY	339.00	-
1	LEFT FRONT DOOR LOCK	FAULTY	196.00	196.00
1	LEFT FRONT DOOR HINGE	NOT NECESSARY	115.00	-
1	LEFT FRONT FENDER	TO REPAIR SEE LABOUR	798.00	-
1	CENTRE LEFT C PILLAR	NOT NECESSARY	1,122.00	-
1	LEFT FRONT DOOR WEATHER STRIP	NECESSARY	166.00	166.00
1	LEFT FRONT DOOR HANDLE	NOT NECESSARY	244.00	-
	LESS 10% DISCOUNT		-742.70	-358.90
			6,684.30	3,230.10
	LABOUR			
	TO FIX & DISMANTLE AND REMOVE DAMAGED LEFT PORTIONS; AFFECTED DAMAGED PORTION. INCLUSIVE OF THE REPAIR OF LEFT FRONT FENDER.		800.00	500.00
	TO CHECK WIRING.		180.00	30.00
	WELDING AND CUTTING OF AFFECTED PANELS, INCLUDING CHASSIS ALIGNMENT.	NOT NECESSARY	1,250.00	-
	SPRAY PAINTING FOR LEFT FRONT TO REAR PORTIONS AFFECTED PARTS.		1,000.00	600.00
			3,230.00	1,130.00
	GRAND TOTAL		9,914.30	4,360.10

Report Ref No. CS3/INC22004380/Tqy3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	3,400.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS3/INC22004380/Tqy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

ANG BRYAN TANI

Automotive Assessor / Investigator

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.