

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	NTUC INCOME IN:	SURANCE CO-OPERATIVE LTD		Ref:	CS3/INC22004387/y3
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	10/05/2022
				Code:	INC
1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMT 9215D	Veh. Inspected		SLD 2821X
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1171706-002	Excess (\$)		0.00
	Assign From	JESS TOH	Assign Date		10/05/2022
2. Vehicle Particulars & Condition					
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	Steering			
	Brakes	Modification			
	General				
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.	Description of Damages				
5.	General Information				
	Accident Date	08/05/2022	Inspection Dat	е	11/05/2022
	Survey held at	GARAGE 13 PTE LTD			
	8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.				
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				