



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR21011644/Gty3e2-1	
			Date: 25/05/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHB 5175R	Veh. Inspected	FBM 4641G
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/11/21/2011	Excess (\$)	0.00
	Assign From	JOEY	Assign Date	10/05/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	YAMAHA CZD300A / XMAX300	c.c	292
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	MH3SH081000016670	Colour	WHITE
	Odometer	42591 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	120/70-15	PIRELLI	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	150/70-14	PIRELLI	6 mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	08/11/2021	Inspection Date	16/11/2021
	Survey held at	KENG HOCK MOTOR 188 YIO CHU KANG ROAD, SINGAPORE 545635		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	