



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: KHONG LYNN			Ref: CS/ASM22004398/Uvy3e2 Date: 12/07/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SML 5081R	Veh. Inspected	SMQ 534H
	Policy No.	GA487096	Coverage (\$)	0.00
	Claim No.	S2M040MT	Excess (\$)	0.00
	Assign From	KHONG LYNN	Assign Date	11/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MR2B23F3201191560	Colour	SILVER
	Odometer	167472 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	CST	7 mm
	L/H Front Tyre	185/60 R15	CST	7 mm
	R/H Rear Tyre	185/60 R15	CST	7 mm
	L/H Rear Tyre	185/60 R15	CST	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/05/2022	Inspection Date	11/05/2022
	Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	