COMFORTDELGRO

			1.0	
EN	GIN	IEER	NG	1

Our Job Ref No :

305515218

Date

19.05.2022

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

FINA	LIZAT	ION FORM		
То	: 2	LKK	Fax:	
Attn	1	TAUFIKH		
Vehic	de Reg	No. : <b>SHD3482G</b>		09.05.2022
The	survey	and estimates of the repairs of the above-mer	ntioned vehicle are as follow	s:-
Z	The r	repair job shall bill to:	TOKIO	SJU750P
2.	The f	inalized amount shall be:		
	(a)	Spare Parts after List discount		\$433.60
	(b)	Labour Charges		\$641.00
		Total for Part-By-Part Repair Cost		\$1,074.60
	(c.)	Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost		£
3.	Estim	nated normal period for repairs:	working days.	
4.		hall treat the above amount as Correct and rking days	Confirmed if there is no r	eply from you within
5.	Thank you for you assistance.		We confirm the e finalized amount	
	Signa	iture:	Signature:	taufikh
	Name	CHIANG	Name :	Taufikh
	Tel	62148314	Date : 3	30/5/22
	Fax	65468156		

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	<u> </u>	N		
3. Survey Fees		349		
4. LTA Search Fee	\$7.49/\$2.00	YES		
<ol><li>Medical Fees (on behalf of driver, if applicable)</li></ol>				
6 Overrun				

ternarks:				
				_



## COMFORTDELGRO ENGINEERING PTE LTD

Date: 19.05.2022

REPAIR ESTIMATE

Time: 11:15:46 Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

**CUSTOMER: 7010045** 

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

**SINGAPORE SINGAPORE 575717** 

65508755

JOB NO

305515218

REGN NO

: SHD3482G

MILEAGE

000000000

MAKE

**HYUNDAI** 

MODEL

IONIQ(G3)

DATE OF REGN

: 18.03.2020

DATE/TIME IN

: 09.05.2022 10:30

ACCIDENT DATE : 09.05.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2533-G MOULDING ASSY-RR BUMPER C 1 451.25 20.00 361.00

0002 04-01-0101-0111-G BUMPER COVER CLIP REAR 10 L 22.00 20.00 17.60

0003 28-01-0104-2029-A VEHICLE NUMBER PLATE REAR 1 55.00 2.00- 55.00

SUB-TOTAL : 433.60

JOB NATURE

0000 PB

PANEL BEATING SHD3482G TP

350.00

0001 SP

SPRAYPAINT CHARGE

250.00

<u>የኅን</u>2 20-22

REMOVE/REFIX REVERSE SENSOR

30.00

0003 L

MERIMEN FEE

11.00

SUB-TOTAL: 641.00

**AUTHORISED: YES/NO** 

TOTAL : 1,074.60

**SURVEYOR NAME & SIGNATURE** 

DATE:

DATE:

**MVA NAME & SIGNATURE**