



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22004407/Any3e2	
			Date: 12/07/2022	
			Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLP 5711Y	Veh. Inspected	SND 8114R
	Policy No.		Coverage (\$)	0.00
	Claim No.	BALAISCL2022-00015FR	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	11/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA NOAH HYBRID	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	ZWR800512233	Colour	BLACK
	Odometer	29043 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	GOODYEAR	6 mm
	L/H Front Tyre	195/65 R15	GOODYEAR	6 mm
	R/H Rear Tyre	195/65 R15	GOODYEAR	6 mm
	L/H Rear Tyre	195/65 R15	GOODYEAR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/04/2022	Inspection Date	11/05/2022
	Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	