



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22004435/y3 Date: 11/05/2022 Code: LPC2	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	XE 2621J	Veh. Inspected	SLM 6702H
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/22/22/VC00/025777	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	11/05/2022
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	09/05/2022	Inspection Date	12/05/2022
	Survey held at	SIN HENG LONG MOTOR WORK BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-287/305 SINGAPORE 569535		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			