

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURA	NCE BHD		Ref:	CS3/LPC22004438/Rvy3e2	
	300 BEACH ROAD SINGAPORE 1995		Date:	24/05/2022		
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBF 3444C	Veh. Inspected	l	SMW 4581M	
	Policy No.	Z21VC05008391	Coverage (\$)		0.00	
	Claim No.	21/22/22/VC05/025722	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		27/04/2022	
2.	. Vehicle Particulars & Condition					
	Make & Model	VOLKSWAGEN GOLF A7 1.4	c.c		1395	
	Engine No.	HIDDEN	Year of Reg.		2013	
	Chassis No.	WVWZZZAUZDW099234	Colour		GREY	
	Odometer	78878 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/40 R18	GOODYEAR		6 mm	
	L/H Front Tyre	225/40 R18	GOODYEAR		6 mm	
	R/H Rear Tyre	225/40 R18	GOODYEAR		6 mm	
	L/H Rear Tyre	225/40 R18	GOODYEAR		6 mm	
4.	Description of Damages					
	THE VEHICLE SU	SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
5.	General Information					
	Accident Date	26/04/2022	Inspect Date /	Time	27/04/2022 ( 02:50 PM )	
	Survey held at	GARAGE 13 PTE LTD				
		8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22004438/Rvy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser