

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

37 LOYANG WAY SINGAPORE 508734

VEHICLE NO : GBH6755A

MAKE & MODEL : NISSAN / NV350 PANEL VAN 2.5 MT 5DR

CHASSIS NO : JN1MC2E26Z0008945

DATE : 07 JULY 2023

CLAIM TYPE : TP CLAIM

D.O.A : 09 APR 2022

TO : ALLIANZ

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	NETT PRICE	TOTAL NETT PRICE
1	1	SLIDE DOOR LH / DD		\$ 1,430.10	\$ 1,430.10
2	1	SLIDE DOOR WEATHERSTRIP LH XSVL		\$ 204.30	\$ 204.30
3	1	SLIDE DOOR ROLLER LWR LH XSVL		\$ 183.30	\$ 183.30
4	1	REAR FENDER LH DD x R		\$ 2,711.50	\$ 2,711.50
5	1	CENTER PILLAR LH XR		\$ 1,429.70	\$ 1,429.70
				\$ 5,958.90	\$ 5,958.90

TOTAL PRICE	\$	5,958.90
LESS 10%	\$	595.89
SUB TOTAL PRICE	\$	5,363.01

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	SLIDING DOOR TRIM CLIPS SET / NLC		\$ 50.00	\$ 50.00
2	1	REAR BUMPER CLIP SET ANC		\$ 50.00	\$ 50.00
3	1	SEALANT / NLC		\$ 80.00	\$ 80.00
TOTAL S/NETT				\$ 180.00	\$ 180.00

Labour Charges

1	To cut/weld panel, knock & align door, to remove/replace damaged parts.	\$ 1,400.00	850
2	To apply anti rust coat and Tuff Kote affected areas	\$ 100.00	50
3	To check and rectify lighting & wiring.	\$ 50.00	30
4	To Spray painting Front & Rear Portions & LH Side Portions.	\$ 1,200.00	700
5	To transfer slide door LH components.	\$ 100.00	50

TOTAL LABOUR

Total Cost of Repairs

(Total parts + Total S/Nett + Total Labour Cost)

\$	2,850.00
\$	8,393.01

NAZ LKK

7/7/2023 1745

(1)

5 Days

CHECK AFTER REPAIR

AFTER REPAIR PHOTOS

LKK Auto Consultants and notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date: