



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3566Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER COVER	TO REPAIR SEE LABOUR	553.00	-
2	REAR BUMPER BRACKET SIDE LH/RH @\$35.60	NOT NECESSARY	71.20	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
2	REAR BUMPER REFLECTOR LH/RH @\$32.00	NOT NECESSARY	64.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
1	REAR BUMPER UNDER COVER	DEFORMED	228.00	228.00
1	BOOTLID	BENT	2,609.80	2,609.80
1	BOOTLID LOWER GARNISH	NOT NECESSARY	227.90	-
2	BOOTLID HINGES LH/RH @\$142.30	NOT NECESSARY	284.60	-
1	BOOTLID MOULDING	CUT	85.00	85.00
1	BOOTLID CRDI	NECESSARY	52.40	52.40
1	BOOTLID EMBLEM I40	NECESSARY	67.90	67.90
	LESS 20% DISCOUNT		-938.84	-613.02
			3,755.36	2,452.08
<u>SPECIAL NETT ITEMS</u>				
1	BOOTLID CITYCAB & TEL NO.STICKER (SN)	NECESSARY	60.00	60.00
1	REVERSE SENSOR (SN)	NOT WORKING	135.70	135.70
			195.70	195.70
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER COVER.		600.00	420.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
	CHECK LIGHTING.	NOT NECESSARY	60.00	-
	TUFF KOTE.		90.00	30.00
			1,410.00	980.00
GRAND TOTAL			5,361.06	3,627.78



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,900.00
---	--	--	-----------------

Report Ref No. CS/AIS22004441/Tqy3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.