

HT

SJE : _____

Date of Survey : _____

Date of ReSurvey: _____

Contacts : _____

Vehicle Nos : **SCP 2799 X**

Model : Toyota Picnic

Year : 2006

Chassis No : JTEGH23B000021961

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	TAILGATE	1	\$ 1,375.90	\$ 1267 ✓ 1,375.90
2	TAILGATE LOGO	1	\$ 143.20	\$ 70 ✓ 143.20
3	TAILGATE EMBLEM "TOYOTA"	1	\$ 108.60	\$ 75 ✓ 108.60
4	TAILGATE EMBLEM "PICNIC"	1	\$ 105.30	\$ 70 ✓ 105.30
5	TAILGATE INNER TRIM BOARD	1	\$ 498.20	\$ 498.20
6	TAILGATE INNER LOCK	1	\$ 404.80	\$ 246 ✓ 404.80
7	TAILGATE WEATHERSTRIP	1	\$ 188.30	\$ ✓ 188.30
8	TAILGATE WINDSCREEN MOULDING	1	\$ 187.90	\$ ✓ 187.90
9	REAR BUMPER	1	\$ 1,352.00	\$ 586 ✓ 1,352.00
10	REAR BUMPER REFLECTOR	2	\$ 80 213.40	\$ 160 ✓ 426.80
11	REAR BUMPER SUPPORT BRACKET	2	\$ 137.40	\$ 274.80
12	REAR BUMPER TOW CAP	2	\$ 186.20	\$ 372.40
13	REAR END PANEL	1	\$ 812.50	\$ 584 ✓ 812.50
14	REAR END PANEL TOP GARNISH	1	\$ 321.00	\$ 321.00
15	REAR FLOOR PANEL	1	\$ 1,025.30	\$ 1,025.30
16	REAR FLOOR PANEL TOP BOARD	2	\$ 580.70	\$ 1,161.40
17	REAR FLOOR PANEL TOP SIDE BOARD	2	\$ 318.00	\$ 636.00
18	REAR FLOOR PANEL TOP BOARD REAR GARNISH	1	\$ 398.00	\$ 398.00
			Parts Sub Total :	\$ 9,792.40
			Discount :	\$ 2,448.10
			PARTS TOTAL :	\$ 7,344.30

25%

BT ✓
 NEC ✓
 NDI ✓
 JM ✓
 TN ✓
 NEC ✓
 BR ✓
 BR ✓
 US ✓
 ND ✓
 DD ✓
 NDI ✓
 3434.20
 -25%
 2575.65

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	SUNDRIES	1	\$ 80.00	\$ 80.00	NNX
2	TAILGATE SEALANT	1	\$ 100.00	\$ 30.00 ✓ 100.00	NECV
3	TAILGATE INNER TRIM BOARD CLIPS	1	\$ 50.00	\$ 50.00	NNX
4	TAILGATE WINDSCREEN SEALANT	1	\$ 100.00	\$ 40.00 ✓ 100.00	NECV
5	TAILGATE WINDSCREEN INNER SEAL	1	\$ 80.00	\$ 80.00	} NNX
6	TAILGATE WINDSCREEN PRIMER & CLEANER	1	\$ 60.00	\$ 60.00	
7	REAR BUMPER CLIPS	1	\$ 50.00	\$ 20.00 ✓ 50.00	} NECV
8	REAR BUMPER SIDE RETAINER	2	\$ 85 186.70	\$ 170 ✓ 373.40	
9	REAR BUMPER REVERSE SENSOR	3	\$ 200.00	\$ 200.00 ✓ 600.00	
10	REAR END PANEL SEALANT	1	\$ 100.00	\$ 30.00 ✓ 100.00	} NNX
11	REAR END PANEL TOP GARNISH CLIPS	1	\$ 50.00	\$ 50.00	
12	REAR FLOOR PANEL SEALANT	1	\$ 100.00	\$ 100.00	
13	REAR FLOOR PANEL INSULATOR	1	\$ 250.00	\$ 250.00	
SPECIAL NETT TOTAL :				\$ 1,993.40	490

Nos.	LABOUR	S\$	
1	R&R TAILGATE COMPONENT	\$ 80.00 ✓ 150.00	} NNX
2	R&R TAILGATE WINDSCREEN	\$ 120.00 ✓ 250.00	
3	R&R REAR BUMPER REVERSE SENSOR	\$ 60.00 ✓ 100.00	
4	CHECK WIRING	\$ 100.00	
5	UPHOLSTERY	\$ 300.00	} NNX
6	PANEL BEATING	\$ 800.00 ✓ 1,400.00	
7	RUST PROOFING	\$ 200.00	
8	SPRAY PAINTING	\$ 600.00 ✓ 1,400.00	
LABOUR TOTAL :		\$ 3,900.00	1660

Survey 12/5/2022
 1200 hrs
 Tatum M
 Resurvey 13/5/2022
 1300 hrs
 Tatum M

Lumpsum repair
 Repair days 8

PARTS TOTAL : \$ 7,344.30
 SPECIAL NETT TOTAL : \$ 1,993.40
 LABOUR TOTAL : \$ 3,900.00
GRAND TOTAL : \$ 13,237.70

4725.65

L/S - 3780.52
 = 3800

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: