




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOH CYNTHIA			Ref: CS3/ASM22004459/Gvy3e2 Date: 24/05/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 3892Y	Veh. Inspected	FBC 7898R
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M03SLZ	Excess (\$)	0.00
	Assign From	LOH CYNTHIA	Assign Date	12/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA T135	c.c	135
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	5YP300090	Colour	WHITE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	70/90-17	TIMSUN	5 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	80/80-17	TIMSUN	5 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION.			
5. General Information				
	Accident Date	30/12/2021	Inspect Date / Time	12/05/2022 (01:00 PM)
	Survey held at	EQBH PTE LTD 25 KAKI BUKIT ROAD 4 #03-46 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

Report Ref No. CS3/ASM22004459/Gvy3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.