

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 3792X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR FENDER ARCH RH	CUT	210.00	210.00
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	592.00	-
1	REAR LOWER ARM RH	BENT	298.00	298.00
1	REAR TIE ROD RH	NOT NECESSARY	145.00	-
1	REAR WHEEL BEARING RH	DAMAGED	278.00	278.00
1	REAR KNUCKLE ARM RH	NOT NECESSARY	398.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,030.00	-
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	115.00	-
1	REAR BUMPER LOWER	CUT	620.00	465.00
1	REAR BUMPER LOWER REFLECTOR RH	NOT NECESSARY	355.00	-
1	REAR BUMPER LOWER REFLECTOR COVER RH	NOT NECESSARY	291.00	-
	LESS 25% DISCOUNT		-1,083.00	-312.75
			3,249.00	938.25
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	120.00	-
1	REAR 18' TYRE RH (SN)	CUT	350.00	250.00
1	REAR SPORT RIM RH (SN)	CUT	980.00	680.00
			1,450.00	930.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		1,600.00	350.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED.		1,400.00	200.00
	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGE AREAS AND CHECK FOR PROPER FUNCTION.	NOT NECESSARY	150.00	-
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	180.00	-

Report Ref No. CS/SMO22004469/Any3e2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT TEST.		120.00	80.00
			3,450.00	630.00
	GRAND TOTAL		8,149.00	2,498.25

RECOMMENDED COST OF LUMP SUM REPAIRS	2,000.00
(TO ITS PRE-ACCIDENT CONDITION)	·

Report Ref No. CS/SMO22004469/Any3e2



**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.