



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22004474/Bqy3e2 Date: 06/02/2023 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMD 6027J	Veh. Inspected	SMS 5987R
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10015081/JT	Excess (\$)	0.00
	Assign From	SHAFAWATI MD RABU	Assign Date	12/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA C-HR 1.8	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	ZYX102174029	Colour	BROWN
	Odometer	170990 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R17	DAVANTI	6 mm
	L/H Front Tyre	215/60 R17	DAVANTI	6 mm
	R/H Rear Tyre	215/60 R17	DAVANTI	6 mm
	L/H Rear Tyre	215/60 R17	DAVANTI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/05/2022	Inspection Date	12/05/2022
	Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	