



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Tang Kim Guan
132 Lorong Ah Soo
#10-412
Singapore 530132

*NOT Withheld
11 Pgs @
Punary After Pain
2 days*

Dear sir
Estimate cost of repair to vehicle no. SDL 1528C
To supply

1. rear bumper	Bu 676.90	✓
2. Rear bumper sensor	sen 350.00	✓
3. Rear bumper reflector left	lt 69.60	✓
4. Rear bumper retainer x2	dis 221.80	✓
5. Rear panel	R 675.60	✓
6. Exhaust box	n 1.089.80	X
7. Tail lamp	• 489.60	✓
Labour charge		
Rust proofing	nn 80.00	X
Panel beating	650.00	200
spray painting	600.00	220
Total		

250

Your faithfully

ALBERT POON

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: