



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

CS3/ASM21004821/Gqy3-1

Affiliated to Federation Internationale Des Experts En Automobile CS3/ASM21004821/Gqy3-1

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Ref: ~~CS3/ASM21004821/Gqy3-1~~
Date: ~~16/04/2021~~ 12/05/2022
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 5702U	Veh. Inspected	FBS 3426L
Policy No.		Coverage (\$)	0.00
Claim No.	S1M03860	Excess (\$)	0.00
Assign From	JOHNNY YONG (SMART CLAIMS) HENG XIN YI (SEA HONG)	Assign Date	16/04/2021 12/05/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	14/04/2021	Inspection Date	16/04/2021
Survey held at	CANDYMOTOR WORKSHOP PTE LTD 25 KAKI BUKIT ROAD 4 #01-83 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.