

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#03-03 SINGAPORE LAND TOWER
SINGAPORE 048623

TEL: 64616555 FAX: 62213147
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 11/05/2022
TP Veh Reg No: SJZ8114Y

Estimate No: EST2200152

Date: 17 May 2022

Veh Reg No: **SNE3675R**

Make/Model: HONDA FIT 1.3 HOME
CVT

Chasis No: GR11105709

Reg. Date: 08/03/2022

Your Ref No: SJZ8114Y

Estimate Repair Cost to Vehicle No :SNE3675R

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Supplementary Parts to Repair		
	List Price		
1	1 PC TOOL TRAY SPONGE	285.40	
2	1 PC REAR BUZZER	121.70	
3	1 PC REAR KEYLESS SENSOR	188.20	
		595.30	
	Less 20%	119.06	476.24
	Total		S\$ 476.24
	GST Amount		S\$ 33.34
	Total Amount Payable		<u>S\$ 509.58</u>

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE