



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC22000632/Vty3e2-1	
			Date: 05/07/2022	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJS 1959J	Veh. Inspected	SLK 2343Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	21/22/22/VP05/025382	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	13/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS HYBRID	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTDKB3FU403544059	Colour	WHITE
	Odometer	169560 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	KUMHO	6 mm
	L/H Front Tyre	195/65 R15	KUMHO	6 mm
	R/H Rear Tyre	195/65 R15	KUMHO	6 mm
	L/H Rear Tyre	195/65 R15	KUMHO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/01/2022	Inspection Date	18/01/2022
	Survey held at	A-TEC AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	