Our Ref: GBC8051K220506		Date: 22/05/2022					
Your Ref:							
China Taiping Insurance (Singapore) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Department							
Dear Sir / Madam							
Traffic Accident Along SLE Involving GBC8051K and PA8146R On 06/05/2022							
We/I, <u>Goldbell Leasing Pte Ltd</u> (NRIC / ROC No: <u>19900</u> m/vehicle - <u>GBC8051K</u> at all material times of the above ac by " <u>China Taiping</u> " authorized appraiser and we/I based ou for S\$ <u>3,200-00</u> being the repair for <u>04</u> Days (Strictly on a	cident. Ou ur/my clai	nr/my vehicle was surveyed ms on his recommendation					
We/I have ascertained that you were the insurers of the driver of same was involved in the aforesaid accident with our/my m/veh							
We/I whereby you are the insurers of m/vehicle PA8146R at solely by the negligence of your insured and as a result there of the has suffered loss and damage as follows:							
Cost of repairs LOU for pre-repair notice 02 days @ S\$ 80-00 [2986 cc] LOU Fee for 04 days @S\$ 80-00 [2986 cc] Rental Fee Invoice No: GIA / LTA search fee Towing Fee (Cash Sale No) Survey Fee	S\$	3,200-00 160-00 320-00 2-00					
Total Amount	S\$	3,682-00					
We/I enclose herewith copies of the supporting documents for vehicle no. GBC8051K as follows: (i) Motor Accident Report & Documents; (ii) Repair Invoices;							
Kindly look into the matter and let us/me hear from you on the as possible.	settlemen	t of our/my claims as soon					
Please remit us/me your settlement sum in favor of M/s Liu's Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBa							
Thank you.							
Yours faithfully,							
<u>f</u>							
The owner of m/vehicle GBC8051K Messers Goldbell Leasing Pte Ltd cc. Liu's Bro Auto Engineering Workshop							

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

liusbro@ymail.com Tel: 67411730

FINAL BILL

Name: China Taiping Insurance (Singapore) Pte Ltd

Address Motor Claims Department 3 Anson Road #16-00

> **Springleaf Tower** Singapore 079909

Ref Date: Ref No: Vehicle No: Model / Make:

UEN No: 53291793J

22/05/2022 GBC8051K220506

> GBC8051K Toyota Hiace

> > Manual

Item #	Damaged Area	Description	Uı	nit Price	Qty		timation / uotation	N / SN		ost Of Lepair
1	Rear	Tailgate	\$:	2,050.00	1	\$	2,050.00		\$	-
2		Tailgate Lock	\$	359.00	1	\$	359.00		\$	-
3		Tailgate Weatherstrip	\$	387.90	1	\$	387.90		\$	-
4		Tailgate (Top) Side Mirror	\$	234.80	1	\$	234.80		\$	-
5		Tailgate Wiper Motor	\$	604.40	1	\$	604.40		\$	-
6		Tailgate Wiper Arm	\$	98.00	1	\$	98.00		\$	-
7		Tailgate Wiper Blade	\$	60.20	1	\$	60.20		\$	-
8		Tailgate Number Plate (Metal)	\$	35.00	1	\$	35.00		\$	-
9		Tailgate Number Plate Lamp Outer Garnish	\$	346.50	1	\$	346.50		\$	-
10		Tailgate "TOYOTA Logo" Motif	\$	70.50	1	\$	70.50		\$	-
11		Tailgate "70 KM/H" Sticker	\$	15.00	1	\$	15.00	SN	\$	-
12		Tailgate "8 pax" Sticker	\$	15.00	1	\$	15.00	SN	\$	-
13		Tailgate Windscreen Glass	\$	1,311.30	1	\$	1,311.30		\$	-
14		Tailgate Windscreen Moulding	\$	219.00	1	\$	219.00		\$	-
15		Tailgate Windscreen Sealant	\$	50.00	1	\$	50.00	SN	\$	-
16		3rd Brake Lamp	\$	234.20	1	\$	234.20		\$	-
17		Tail Lamp	\$	365.10	2	\$	730.20		\$	-
18		Bumper	\$	465.00	1	\$	465.00		\$	-
19		Bumper Clips 1 set	\$	50.00	1	\$	50.00	SN	\$	-
20		Bumper Reverse Sensor	\$	220.00	1	\$	220.00		\$	-
21		End Panel Outer	\$	566.10	1	\$	566.10		\$	-
22		End Panel Sealant	\$	50.00	1	\$	50.00	SN	\$	-
20		To check all wiring & electrical component for				Φ.			φ.	
23		proper function				\$	80.00		\$	-
24		Remove and refix rear tailgate components & wiper mechanism				\$	100.00		\$	-
25		Remove and refix rear bumper reverse sensor				\$	120.00		\$	-
26		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs				\$	700.00		\$	-
27		To putty & spray painting & including touch up paint on accident affected areas				\$	600.00		\$	-
28		To apply Rust Proofing , reseal tuff-coating treatment on accident area				\$	80.00		\$	-
29		Remove & reinstall Tailgate Glass to facilitate repairs				\$	120.00		\$	-
		•								

Total Parts & Labour of estimate for damaged vehicle

\$ 9,972.10

\$ 3,200.00

J	J

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

PA8146R

Date of Accident

06/05/2022

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Period of Insurance Sing...

Period of Insurance 15/01/2022 - 14/01/2023

Requested By Susan Low (Liu's Brother Auto...

Requested Date 13/05/2022 14:17

Payment details

Request Amount: **\$\$1.87** GST Amount: **\$\$0.13**

Total Amount Due (GST Inclusive): \$\$2

General Insurance Association

Records Management Centre
GST Registration No: **M400017735**