



Your Ref: 17/18/18/VC10/267486

Date: 23th Jun 2022

Our Ref: CS1/LPM22004553/Rty3e2

M/s Lonpac Insurance Bhd

21st Flr, Bangunan Public Bank
No. 6 Jalan Sultan Sulaiman
50000 Kuala Lumpur, Malaysia
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLH 7253G
INSURED VEHICLE: JQQ 3348
ACCIDENT DATE: 09/09/2018**

We thank you for your instruction on 17/05/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLH 7253G from M/s T & C Automobile Assessors.
- b) Polis Diraja Malaysia of Vehicles SLH 7253G.
- c) Colour damaged vehicle photographs of SLH 7253G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SLH 7253G
Make & Model : Toyota Harrier Premium 2.0 A
Year of Registration : 2016
Chassis Number : ZSU600087515
Engine Capacity : 1986 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.