

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 12-May-22
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: PC7197P		
MODEL	: TOYOTA HIACE COMMUTER		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 11-May-22
		TIME	: 08:30HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rehd</i>	1	\$ 620.50	\$ 620.50
2	FRONT BUMPER SIDE RETAINER <i>could</i>	1	\$ 110.00	\$ 110.00
3	FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 480.00	\$ 480.00
4	CENTRE GRILLE TOP <i>?</i>	1	\$ 455.60	\$ 455.60
5	CENTREG GRILLE LOWER <i>could</i>	1	\$ 322.40	\$ 322.40
6	CENTREG GRILLE BASE	1	\$ 280.90	\$ 280.90
7	HEADLAMP LH <i>could</i>	1	\$ 2,855.60	\$ 2,855.60
8	HEADLAMP LOWER BRACKET LH <i>could</i>	1	\$ 90.00	\$ 90.00
9	FRONT DOOR LH <i>Reps</i>	1	\$ 1,550.00	\$ 1,550.00
10	FRONT DOOR STEP PANEL LH <i>Reps</i>	1	\$ 280.00	\$ 280.00
11	FRONT DOOR STEP PANEL PROTECTOR LH <i>Missing</i>	1	\$ 130.00	\$ 130.00
12	ADBLUE TANK <i>could</i>	1	\$ 1,055.60	\$ 1,055.60
13	ADBLUE TANK MOTOR <i>Rehd</i>	1	\$ 2,511.50	\$ 2,511.50
14	ADBLUE TANK LOWER BRACKET <i>Best</i>	1	\$ 211.40	\$ 211.40
15	FUSS WIREHARNESS <i>Reps</i>	1	\$ 1,855.20	\$ 1,855.20
16	FUSS WIREHARNESS HOLDER <i>could</i>	1	\$ 155.30	\$ 155.30

757110
5678.32

TOTAL PRICE	\$ 12,964.00
LESS 25%	\$ 3,241.00
SUB TOTAL PRICE	\$ 9,723.00

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
2	FRONT BUMPER LOWER LID <i>Paint</i>	1	\$ 1,200.00	\$ 1,200.00
3	FRONT BUMPER FOGLAMP <i>Missing</i>	1	\$ 400.00	\$ 400.00
4	FRONT DOOR ARCH <i>Repair</i>	1	\$ 550.00	\$ 550.00
5	HEADLAMP CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
6	HEADLAMP STICKER <i>new</i>	1	\$ 80.00	\$ 80.00
7	HEADLAMP LED BLUB <i>new</i>	1	\$ 280.00	\$ 280.00
8	RIM <i>new</i>	1	\$ 1,400.00	\$ 1,400.00
9	ADBLUE <i>new</i>	1	\$ 100.00	\$ 100.00

1990

TOTAL \$ 4,050.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	650	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	800	
3	TUFF COAT	\$ 150.00	60	
4	WIRING CHECK	\$ 280.00	30	
5	TO REMOVE RAND REFIX FRONT DOOR MECHANISM	\$ 180.00	80	
6	FOUR WHEEL ALIGHMENT	\$ 100.00	80	

TOTAL

\$3,510.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 13,773.00
TOTAL LABOUR COST : \$ 3,510.00
TOTAL REPAIR COST : \$ 17,283.00

APPROVED DETAILS

SURVEYOR :
CONTACT NO :

PART BY PART / LUMP SUM :
NO OF DAYS :

FAX :

Admin Lj
4/5 17/05/22

05 Days

bold 9368.32
L/S: 7.5K

7.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: