



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22004557/Kty3e2	
			Date: 24/06/2022	
			Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLV 1081B	Veh. Inspected	SJA 3683K
	Policy No.		Coverage (\$)	0.00
	Claim No.	2022 22004865FR	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	17/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA JAZZ (A)	c.c	1339
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	JHMGD18507S233810	Colour	METALLIC YELLOW
	Odometer	275335 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/55 R15	YOKOHAMA	7 mm
	L/H Front Tyre	185/55 R15	YOKOHAMA	7 mm
	R/H Rear Tyre	185/55 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	185/55 R15	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/05/2022	Inspection Date	17/05/2022
	Survey held at	RC AUTO 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	