



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO22004558/Avy3e2 Date: 17/08/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 3297K	Veh. Inspected	SME 3759U
Policy No.	D20MTPCVE003108	Coverage (\$)	0.00
Claim No.	CMTD2201662/AGC	Excess (\$)	0.00
Assign From	MELVIN YE	Assign Date	17/05/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALPHARD	c.c	2493
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	AGH300184421	Colour	BLACK
Odometer	228481 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/50 R18	BRIDGESTONE	6 mm
L/H Front Tyre	235/50 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	235/50 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	235/50 R18	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/05/2022	Inspection Date	17/05/2022
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	