



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KITTY			Ref: CC4/ASM22004575/Uea3q2 Date: 12/07/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 5038Z	Veh. Inspected	SLE 1340T	
Policy No.	P2459880	Coverage (\$)	0.00	
Claim No.	S2M0416C	Excess (\$)	0.00	
Assign From		Assign Date	17/05/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SUZUKI SWIFT (A)	c.c	1372	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JSAFZC82S00329427	Colour	GREY	
Odometer	420586 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/50 R16	KAPSEN	6 mm	
L/H Front Tyre	205/50 R16	KAPSEN	6 mm	
R/H Rear Tyre	205/50 R16	KAPSEN	6 mm	
L/H Rear Tyre	205/50 R16	KAPSEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/05/2022	Inspection Date	17/05/2022	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	