



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: WINNIE HO			Ref: CS3/ASM22004596/Rvce2 Date: 27/05/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMP 6285S	Veh. Inspected	SGA 8350Z
	Policy No.	P2456142	Coverage (\$)	0.00
	Claim No.	S2M040IG	Excess (\$)	0.00
	Assign From	WINNIE HO	Assign Date	17/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HARRIER G GRADE	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTEKB3GH20J001771	Colour	GREY
	Odometer	97957 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R18	YOKOHAMA	6 mm
	L/H Front Tyre	235/55 R18	YOKOHAMA	6 mm
	R/H Rear Tyre	235/55 R18	YOKOHAMA	6 mm
	L/H Rear Tyre	235/55 R18	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
	Accident Date	28/04/2022	Inspect Date / Time	20/05/2022 (11:23 AM)
	Survey held at	160 SIN MING DRIVE #06-10 SIN MING AUTOCITY		
	Repairer	LIAN HENG PAINTER CO.		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

Report Ref No. CS3/ASM22004596/Rvce2

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.