

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

EQ Insurance Company Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	14/05/2022
Vehicle Reg. No.:	SHA5389X	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	06/09/2018
Vehicle Colour:	BLUE		
Engine No:	G4LEJU081014	Chassis No:	KMHC851CVKU107483
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	5,352.28
Miscellaneous Items	0.00
Labour	3,130.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	8,482.28
+ GST 7.00% (\$\$)	593.76
Nett Amount (\$\$)	9,076.04

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 May 2022)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA5389X/17/05/2022 14:33

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID / <i>Inc</i>			
2	1		*BOOTLID LOCK LOWER - <i>BT</i>	20.00	0.00	*2,549.70 FL
3	1		*BOOTLID EMBLEM - H	20.00	0.00	*51.30 FL
4	1		*BOOTLID EMBLEM - HYBRID	20.00	0.00	*28.00 FL
5	1		*BOOTLID EMBLEM - IONIQ	20.00	0.00	*24.30 FL
6	1		*BOOTLID COMFORT LOGO	20.00	0.00	*31.30 FL
7	1		*BOOTLID COMFORT TEL.NO. LOGO	0.00	0.00	*30.00 F
8	1		*BOOTLID APPS LOGO	0.00	0.00	*30.00 F
9	2		*REAR WINDSCREEN SEALANT	0.00	0.00	*40.00 F
10	1		*ANTENNA ASSY - SMARTK ✓ <i>NW</i>	0.00	0.00	*46.00 F
11	1		*REAR FOG LAMP / <i>Cut</i>	20.00	0.00	*40.50 FL
12	1		*REAR NUMBER PLATE - <i>BT</i>	20.00	0.00	*201.50 FL
13	1		*REAR BUMPER ASSY - <i>Dis</i>	0.00	0.00	*50.00 F
14	1		*REAR BUMPER REINFORCEMENT BEAM - <i>BT</i>	20.00	0.00	*459.40 FL
15	1		*REAR BUMPER REINFORCEMENT BRACKET LH ✓ <i>BT</i>	20.00	0.00	*394.80 FL
16	1		*REAR BUMPER REINFORCEMENT BRACKET RH ✓ <i>BT</i>	20.00	0.00	*138.10 FL
17	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	*138.10 FL
18	1		*REAR BUMPER CENTRE LOWER MOULDING - <i>mis</i>	20.00	0.00	*451.25 FL
19	1		*REAR BUMPER SIDE BRACKET LH ✗	20.00	0.00	*155.00 FL
20	1		*REAR BUMPER SIDE BRACKET RH ✗ <i>NEC</i>	20.00	0.00	*55.80 FL
21	10		*REAR BUMPER CLIPS / <i>acc</i>	20.00	0.00	*55.80 FL
22	1		*REAR BUMPER UNDER CENTRE COVER ✗ <i>mis</i>	20.00	0.00	*22.00 FL
23	1		*REAR BUMPER UNDER SIDE LH COVER ✗ <i>mis</i>	20.00	0.00	*255.00 FL ✗
24	1		*REAR BUMPER TOW COVER - <i>mis</i>	20.00	0.00	*108.00 FL ✗
25	1		*REVERSE ESENSOR ✓ <i>mis</i>	20.00	0.00	*98.80 FL
26	1		*REAR END PANEL ✓ <i>BUC</i>	0.00	0.00	*180.00 F
27	1		*REAR END PANEL GARNISH / <i>ee</i>	20.00	0.00	*532.00 FL
28	1		*REAR REFLECTOR LH	20.00	0.00	*346.80 FL
29	1		*REAR REFLECTOR RH - <i>mis</i>	20.00	0.00	*41.45 FL
				20.00	0.00	*41.45 FL

F=Franchise part. L=ListitemDisc.

Sub Total (\$\$) 5857.35 6,596.35

- List Item Discount on L Items (\$\$) 1,244.07

Total Parts (\$\$) 4685.88 5,352.28

ComfortDelGro Engineering Pte Ltd/SHA5389X/17/05/2022 14:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	1,500.00 700
2	SPRAYPAINT	New	900.00 750
3	CHECK WIRING	New	50.00 30
4	TUFF KOTE	New	50.00 X 2
5	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00 100
6	REMOVE/REFIX REVERSE SENSOR	New	60.00 40
7	ADVERTISEMENT LOGO - FENDER	New	200.00 -
8	ADVERTISEMENT LOGO - BOOTLID	New	100.00 -
9	TOWING FEE - KING DOLLY	New	150.00 ✓
Gross Labour Cost (S\$)			2070 3,130.00

ComfortDelGro Engineering Pte Ltd/SHA5389X/17/05/2022 14:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

7131.88

-20%: 5700

4 Days.
L/S
After repair photos.
Gmo Repair
18/5/22
12:15 pm.

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices based on "market price"
- Third party claims on "no-fault" basis
- No illegal modification
- Supplemental claims are allowed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: