

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |  |                 |                       |
|---|--|--|-----------------|-----------------------|
|   | MS FIRST CAPITA  | L INSURANCE LTD                            | Ref:            | CS/FCI22004651/Kty3e2 |
|   | 36 ROBINSON RO<br>#16-01 CITY HOUS   | AD<br>SESINGAPORE 068877                   | Date:           | 15/06/2022            |
|   |  |  | Code:           | FCI2                  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM  |  |                 |                       |
|   | Insured Veh.   | YN 9007C                                   | Veh. Inspected  | SDS 4333R             |
|   | Policy No.   |  | Coverage (\$)   | 0.00                  |
|   | Claim No.  | D22001486MFCV                              | Excess (\$)     | 0.00                  |
|   | Assign From  | HARMINDER KAUR                             | Assign Date     | 18/05/2022            |
| 2. Vehicle Particulars & Condition                                |  |  |                 |                       |
|   | Make & Model   | NISSAN GT-R (A)                            | c.c             | 3799                  |
|   | Engine No.   | HIDDEN                                     | Year of Reg.    | 2008                  |
|   | Chassis No.  | R35005477                                  | Colour          | METALLIC GREY         |
|   | Odometer   | 32557 KM                                   | Steering        | IN ORDER              |
|   | Brakes   | IN ORDER                                   | Modification    | SPORTS RIM            |
|   | General  | GOOD                                       |                 |                       |
| 3. Conditions of Tyres  |  |  |                 |                       |
|   |  | Size                                       | Make            | Balance               |
|   | R/H Front Tyre   | 255/40Z R20                                | DUNLOP          | 5 mm                  |
|   | L/H Front Tyre   | 255/40Z R20                                | DUNLOP          | 5 mm                  |
|   | R/H Rear Tyre  | 285/35Z R20                                | DUNLOP          | 7 mm                  |
|   | L/H Rear Tyre  | 285/35Z R20                                | DUNLOP          | 7 mm                  |
| 4.  | Description of Damages   |  |                 |                       |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.   |  |                 |                       |
|   | DAMAGES SEE DETAILS.   |  |                 |                       |
| 5.  | General Information  |  |                 |                       |
|   | Accident Date  | 13/05/2022                                 | Inspection Date | 01/06/2022            |
|   | Survey held at   | ALAN'S UNITED AUTO PTE LTD                 |                 |                       |
|   |  | BLK 7 SIN MING INDUSTRIAL ESTATE<br>#01-76 |                 |                       |
|   |  | #01-76<br>SINGAPORE 575642                 |                 |                       |
| 5a.   | Remarks  |  |                 |                       |
|   | A)DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |                       |
| 5b.   | Estimate Days of Repair  |  |                 |                       |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days   |  |                 |                       |
|   |  |  |                 |                       |