

Mei Kwan (LKKAuto)

From: Zoom Autowerks <zoomautowerks@gmail.com>

Sent: Monday, 16 May 2022 1:08 PM

To: SUR <sur@lkkauto.com>

Subject: Pre-Repair Inspection for SMQ 7015 T // Accident on 14/05/2022 @ 17:41HR at along Tiong Bahru Road x Redhill Close involving Vehicle Number SMQ 7015 T & SFH 9828 T

Dear Sir/Madam,

We are instructed by Yue Hock Lim to notify you of a road traffic accident on 14/05/2022

at about 17:41HR along Tiong Bahru Road x Redhill Close involving our client's vehicle registration number SMQ 7015 T and vehicle registration number SFH 9828 T driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 13 Kaki Bukit Road 4, Bartley Biz Centre, #01-24, Singapore 4178 08.

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -