

TECHNEAT PTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996

Fax : (65) 6384 1996

Hotline : (65) 9691 0887

Email: techneatcarcare@yahoo.com.sg

Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment

Work Order: SMQ 7015 T

18.5.22 16:01

Hyundai : Avante/Elantra/Lantra : AD/ADa/ADi (2016-) : AD : Rest of World

Front : Left

Actual	Before	Specified Range
-0°21'		-0°53' 0°07'
-4°06'		4°00' 5°00'
-0°23'		-0°03' 0°09'
13°30'		13°30' 14°30'
13°09'		12°37' 14°37'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
3°02'		-0°53' 0°07'
-4°06'		4°00' 5°00'
0°50'		-0°03' 0°09'
11°44'		13°30' 14°30'
14°46'		12°37' 14°37'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-3°23'		
0°00'		
1°45'		
0°28'		-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°13'		-1°42' -0°42'
-0°52'		-0°02' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°13'		-1°42' -0°42'
0°51'		-0°02' 0°16'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°11'		
0°00'		-0°04' 0°32'
-0°51'		

TECHNEAT PTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996
Fax : (65) 6384 1996
Hotline : (65) 9691 0887

Email: techneatcarcare@yahoo.com.sg
Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment

Work Order: SMQ7015T
21.5.22 15:50

Hyundai : Avante/Elantra/Lantra : AD/ADa/ADi (2016-) : AD : Rest of World

Front : Left

Actual	Before	Specified Range
-0°23'	-0°35'	-0°53' 0°07'
4°06'	4°05'	4°00' 5°00'
0°09'	-0°13'	-0°03' 0°09'
13°41'	13°53'	13°30' 14°30'
13°19'	13°18'	12°37' 14°37'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°04'	-0°07'	-0°53' 0°07'
4°06'	4°05'	4°00' 5°00'
0°08'	0°02'	-0°03' 0°09'
14°45'	14°48'	13°30' 14°30'
14°42'	14°42'	12°37' 14°37'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°19'	-0°28'	
0°00'	0°00'	
-1°04'	-0°55'	
0°10'	-0°11'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°35'	-1°31'	-1°42' -0°42'
-0°41'	-0°41'	-0°02' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°11'	-1°10'	-1°42' -0°42'
0°43'	0°44'	-0°02' 0°16'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°14'	-0°21'	
0°02'	0°03'	-0°04' 0°32'
-0°42'	-0°43'	