

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building 78 Shenton Way #07-16
079120

Attention : Motor Claim Department
Contact : 6419 3000

Estimate : ES708335

Date : 17/05/2022
Vehicle Num. : SKT 9046Z
Make/Model : TOYOTA WISH
Chassis/Eng# : ZGE206023348
Accident Date : 17/05/2022
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1PC	LIST ITEMS :		
2.	2PCS	FRONT BUMPER		584.70
3.	1PC	FRONT BUMPER SIDE RETAINER	59.57	119.14
4.	1PC	FRONT BUMPER REINFORCEMENT		305.20
5.	1PC	FRONT BUMPER SPONGE		100.00
6.	1PC	N/S FRONT BUMPER FOGLAMP COVER- SMALL		95.00
7.	1PC	N/S FRONT BUMPER FOGLAMP COVER-BIG		145.00
8.	1PC	N/S FRONT FENDER		988.40
9.	1PC	N/S FRONT FENDER INNER SHIELD		178.20
10.	1PC	O/S FRONT FENDER INNER SHIELD		178.20
11.	1PC	RADIATOR GRILLE		398.00
12.	1PC	BONNET LOGO EMBLEM		92.00
13.	1PC	AIR CLEANER AIR DUCT		85.70
14.	1PC	AIR CLEANER AIR DUCT PIPE		128.00
15.	1PC	N/S FRONT LOWER ARM		760.10
16.	1PC	N/S FRONT KNUCKLE ARM		628.40
17.	1PC	N/S FRONT HUB		220.00
18.	1PC	N/S FRONT WHEEL BEARING		167.30
		N/S FRONT SHOCK ABSORBER		340.00
List TotalS\$:				5,513.34
25.00% Discount S\$:				1,378.34
				4,135.00

CONTINUE / ...

Not Authorised
here
unhappy
18/5/22
1/5 \$4000
5 days
Take the Authorisation

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building 78 Shenton Way #07-16
079120

Attention : Motor Claim Department

Contact : 6419 3000

Estimate : ES708335

Date : 17/05/2022

Vehicle Num. : SKT 9046Z

Make/Model : TOYOTA WISH

Chassis/Eng# : ZGE206023348

Accident Date : 17/05/2022

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1SET	SPECIAL NETT ITEMS :		
2.	1SET	FRONT BUMPER CLIP	126	50.00 ✓
3.	1SET	N/S FRONT FENDER INNER SHIELD CLIP	126	50.00 ✓
4.	1SET	O/S FRONT FENDER INNER SHIELD CLIP	11	50.00 X
5.	1PC	N/S FRONT RIM		500.00 X
6.	1PC	N/S FRONT TYRE		250.00 X
7.	1BTL	COOLANT		30.00 X
Special Nett Total S\$:				930.00

LABOUR :

TO CHECK LIGHT AND WIRING
COMPUTERIZED WHEEL ALIGNMENT
ANTI-RUST AND BODY SEALANT
TO VACCUM, REOIL AND REGAS AIR CON
REPLACE FRONT UNDERCARRIAGE

50.00
120.00
120.00
120.00
250.00

LABOUR/PANEL BEATING, REPAIR SUPPORT PANEL AND REPLACE PARTS

900.00

SPRAY PAINTING 1)BUMPER 2)REINFORCEMENT 3)NS FENDER
4)OS FENDER 5)BONNET 6)NS FRONT DOOR 7)SUPPORT PANEL

1,500.00

Labour Total S\$:

3,060.00

E. & O.E.

Total S\$: 8,125.00

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-4128.68
252
3096.57
100
1820
5016.57
204
40.3