

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Allianz Global Corporate & Specialty SE, Singapore Branch

Policy No: SPMF1000000449

Accident Date : 05.05.2022

Date: 14.05.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Kia Cerato" Reg. No SMJ2660A			
1pc	Front Bumper	1.50	285.00
1pc	Front Bumper Clips		18.00
1pc	Front Bumper Bracket RH		12.00
1pc	Front Bumper Sponge		115.00
1pc	Front Bumper Reinforcement		190.00
1pc	Front Bumper Beam		50.00
1pc	Front Bumper Emblem		20.00
1pc	Front Bumper Corner Retainer RH		12.00
1pc	Front Bumper Signal Lamp RH		80.00
1pc	Front Bumper Side Air Grille RH		8.00
1pc	Front Bumper Lower Lip		130.00
1pc	Front Bumper Lower Lip Garnish		60.00
1pc	Front Bumper Fog Lamp RH		120.00
1pc	Front Bumper Air Duct RH		10.00
1pc	Headlamp RH		530.00
1pc	Headlamp Lower Bracket		35.00
1pc	Grille		130.00
1pc	Front Fender RH		160.00
1pc	Front Fender Shield		58.00
1pc	Wiper Tank		65.00
1pc	Wiper Tank Motor		45.00
1pc	Support Panel		325.00
1pc	Front Wheel Rim		350.00
1pc	Front Shock Absorber		115.00
1pc	Front Knuckle Arm		130.00
1pc	Front Knuckle Arm Bearing		180.00
1pc	Front Lower Arm		125.00
			3,358.00
	Cost Plus 10%		335.80
			3,693.80
	To Conduct Electrical Check, Focus Headlamp		30.00
	To Remove / Refit Air Con Condenser & Refill Air Con Gas		120.00
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		60.00
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		180.00
		C/F	4,083.80

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **Allianz Global Corporate & Specialty SE, Singapore Branch**

Policy No: **SPMF1000000449**

Date: **14.05.2022**

Accident Date : 05.05.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Kia Cerato" Reg. No SMJ2660A		
		B/F	4,083.80
	To Conduct Computerize Wheel Alignment Test		80.00
	Labour Charge - Panel Beating, Repairing of Bonnet, Front Chassis, Front Fender Inner Panel & Part Replacement		700.00
	To Respray Affected Areas		650.00
		Total :	5,513.80