



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

Our Ref : GBF5485X

Your Ref : 21/22/22/VC05/025745

LONPAC INSURANCE BHD

300 BEACH ROAD #17-04/07

THE CONCOURSE

SINGAPORE 199555

12 July 2022

Attn: MOTOR CLAIMS DEPT

Dear Sir / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: GBF5485X & GBD2314L ON 30/04/2022 @ 18:10 HRS
ALONG PIE TOWARDS CHANGI

The vehicle had been surveyed by your appointed surveyor and repaired to our client's satisfaction.

We hereby submit the details of claim as follow:

Cost Of Repair	:	S\$ 5,509.43
Loss Of Use (\$ 120.00 x 6 days)	:	S\$ 720.00
Additional Loss Of Use (\$ 120.00 x 1 days)	:	S\$ 120.00
GIA / LTA Search	:	S\$ 7.45
		<u>S\$ 6,356.88</u>

Kindly revert within SEVEN days. Failing which we reserve our rights to refer the matter to our solicitors.

Your kind attention to the matter would be much appreciated.

Yours faithfully,

TONG LUCK AUTO PTE LTD

AUTHORISATION LETTER

I, DAIMLER FLEET MANAGEMENT S'PORE PTE LTD of 1 GATEWAY DRIVE #15-08 WESTGATE TOWER SINGAPORE 608531, owner of GBF5485X hereby authorize TONG LUCK AUTO PTE LTD to act for me with my respect to our claim for repair costs and/or rental and/or loss of use for our vehicle no.: GBF5485X that was damaged pursuant to the accident which occurred on 30/04/2022 ALONG PIE TOWARDS CHANGI involving vehicle nos: GBD2314L

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the

Dated this 18th day of May 2022




Handwritten signature

Signed by third party claimant



TONG LUCK AUTO PTE LTD



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

YOUR REF NO : 21/22/22/VC05/025745

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 30/04/2022

TP VEHICLE NO : GBD2314L

TAX INVOICE

NO : AR202207-0028

CLAIM NO : QUOT202205-000044(01)

DATE : 12/07/2022

POLICY NO : 999995580

VEH REG : GBF5485X

MAKE/MODEL : TOYOTA HIACE VAN TURBO
5 DR

CHASIS NO : JTFHT02P900209071

ENGINE NO : 1KD2660715

REG. DATE : 2016

Final Repair Cost to Vehicle No : GBF5485X

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
LIST PRICE			
1 Tailgate	1	2,168.50	2,168.50
2 Tailgate centre logo	1	72.90	72.90
3 Tailgate lock	1	289.60	289.60
4 Taillamp assy - LH	1	306.90	306.90
5 Rear end panel (outer)	1	442.90	442.90
6 Rear end panel top garnish	1	118.92	118.92
7 Rear bumper	1	399.65	399.65
			<u>3,799.37</u>
		Less 25%	<u>949.82</u>
			<u>2,849.55</u>
SPECIAL NET			
8 Rear windscreen sealant	1	40.00	40.00
9 Tailgate weathestrip (50%)	1	204.45	204.45
10 Tailgate '70km/h' sticker	1	15.00	15.00
11 Rear bumper sensor (set)	1	200.00	200.00
			<u>459.45</u>
LABOUR			
12 To remove and refit rear windscreen glass	1	120.00	120.00
13 To transfer damaged tailgate interior mechanism to new tailgate	1	60.00	60.00
14 To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	700.00	700.00
15 To putty and spray paint on affected areas	1	500.00	500.00
16 To apply rust-proofing on replaced and repaired panels	1	60.00	60.00
17 To supply and paster logo on tailgate	1	400.00	400.00
			<u>1,840.00</u>



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

YOUR REF NO : 21/22/22/VC05/025745

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 30/04/2022

TP VEHICLE NO : GBD2314L

TAX INVOICE

NO : AR202207-0028

CLAIM NO : QUOT202205-000044(01)

DATE : 12/07/2022

POLICY NO : 999995580

VEH REG : GBF5485X

MAKE/MODEL : TOYOTA HIACE VAN TURBO
5 DR

CHASIS NO : JTFHT02P900209071

ENGINE NO : 1KD2660715

REG. DATE : 2016

Final Repair Cost to Vehicle No : GBF5485X

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		TOTAL:	S\$5,149.00
		ADD GST @ 7%:	360.43
		GRAND TOTAL:	<u>S\$5,509.43</u>

SINGAPORE DOLLARS FIVE THOUSAND FIVE HUNDRED AND NINE AND CENTS FORTY-THREE ONLY

TONG LUCK AUTO PTE LTD

E. & O.E.

AUTHORISED SIGNATURE

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 17 May 2022 / 13:47:26

Receipt Date/Time : 17 May 2022 / 13:47:26

Tax Invoice/Receipt

Receipt No. : ITNET-00000-220517-001944

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GBD2314L				
As at 30 Apr 2022/18:10:00				
Insurance Co: LONPAC INSURANCE BHD				
1	Insurance Enquiry - GBD2314L Enquiry Fee 20220517134457035071	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
518834XXXXXX2002		eNETS Credit Card		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Enquire Vehicle's Insurance Particulars

Thank You!

The insurance details of the vehicle you enquired can be found below. If you have entered a valid email address, a copy would have been sent to you.

Vehicle No.

GBD2314L

Incident Date/Time

30 Apr 2022 / 18:10:00

Insurance Company Name

LONPAC INSURANCE BHD

[Save as PDF](#)

[OK →](#)

[Print](#)