



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22004683/Vny3e2	
			Date: 16/08/2022	
			Code: FCI2	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
	<b>Insured Veh.</b>		<b>Veh. Inspected</b>	XD 5813H
	<b>Policy No.</b>	D-22098973MFVS/2	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	D22001327MFVS	<b>Excess (\$)</b>	1,500.00
	<b>Assign From</b>	HARMINDER KAUR	<b>Assign Date</b>	18/05/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	PIERCE SABER	<b>c.c</b>	8849
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2012
	<b>Chassis No.</b>	4P1CS01A7BA011872	<b>Colour</b>	LIGHT GREEN
	<b>Odometer</b>	10166 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	315/80 R22.5	GOODYEAR	6 mm
	<b>L/H Front Tyre</b>	315/80 R22.5	GOODYEAR	6 mm
	<b>R/H Rear Tyre</b>	315/80 R22.5	GOODYEAR	6 mm
	<b>L/H Rear Tyre</b>	315/80 R22.5	GOODYEAR	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	03/05/2022	<b>Inspection Date</b>	19/05/2022
	<b>Survey held at</b>	INDECO ENGINEERS PTE LTD 7 ABINGDON ROAD SINGAPORE 499931		
<b>5a. Remarks</b>				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	