



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref: CS/FCI22004683/Vty3

Date: 18/05/2022

Code: FCI2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	XD 5813H
Policy No.	Coverage (\$)	0.00
Claim No. D22001327MFVS	Excess (\$)	1,500.00
Assign From HARMINDER KAUR	Assign Date	18/05/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	03/05/2022	Inspection Date	19/05/2022
Survey held at	INDECO ENGINEERS PTE LTD 7 ABINGDON ROAD SINGAPORE 499931		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--