

PLEASE ARRANGE TO SURVEY
VEHICLE AT 22 TAMPINES ST 92 (S
528876)

Inthiran Guna
CLAIM DEPARTMENT
DID : 66547607
FAX : 66547540

Date : 18/05/2022

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 5 Accident Date : 09/05/2022

Vehicle No : SMW-2703-S Make & Model : BMW X3 2.0 SDRIVE 20I X LINE (A)

ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	FRONT LH FENDER SCR RESTORE	1,627.70	cut
1	FRONT BUMPER	80.00	40 REC SN
10	FRONT BUMPER CLIP		
	Sub Total	1707.70	
	Discount 5% On Parts	(178.98)	
<u>Labour & Misc</u>			
	LABOUR FRONT AFFECTED PORTION	400.00	/
	PAINTING FRONT AFFECTED PORTION	500.00	400

Date : 18/05/2022
 To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : 5 Accident Date : 09/05/2022
 Vehicle No : SMW-2703-S Make & Model : BMW X3 2.0 SDRIVE 20I X LINE (A)

ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	900.00	

Remarks:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

2,428.71

SUB TOTAL

GST 7.0 % 170.01

TOTAL 2,598.73

Surveyor's name: _____

Principal's name: ETHOZ Group Ltd

Survey Date & Time: _____

Thevan@LKKauto.com

82235769

19/5/22 1630

clerk swp 4/5

1400
 F 1880
 PD. 41