

ComfortDelGro Engineering Pte Ltd (Co.Reg.No.199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

SAS-KIV

Lim Tien Siong

TP INSURER:
CTPL

India International Insurance Pte Ltd (HQ)

CP/P)

Singapore

LKK-

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY
Policy No:
Vehicle Reg. No.: SHC2783A
Party At Fault: UNKNOWNRef. No:
Date of Loss: 17/05/2022
Driveable?Make/Model: HYUNDAI IONIQ HYBRID, 1.6 GLS
DCT (A)
Vehicle Colour: BLUE
Engine No: G4LEKU402403
Odometer: 0 KM

Vehicle Reg. Date: 07/11/2019

Chassis No: KMHC851CVLU188094

Paint Type:
List Item Discount: 20.00 %
Total Loss? NO
Est. Duration of Repair (day) 3

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

	Amount
Parts	2,003.12
Miscellaneous Items	11.00
Labour	820.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$) 2,834.12

+ GST 7.00% (S\$) 198.39

Nett Amount (S\$) 3,032.51

This claim is handled by: LIM TIEN SIONG

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 18 May 2022)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC2783A/18/05/2022 08:52**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER / CHA	20.00	0.00	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT X	20.00	0.00	*394.80 FL
3	2		*REAR BUMPER REINFORCEMENT BRKT RH/LH X SNN	20.00	0.00	*276.20 FL
4	1		*REAR BUMPER CENTRE MOULDING / CHA	20.00	0.00	*451.25 FL
5	1		*REAR BUMPER LOWER MOULDING X SNN	20.00	0.00	*155.00 FL
6	10		*REAR BUMPER CLIPS / ACC	20.00	0.00	*22.00 FL
7	1		*REAR FOGLAMP X	20.00	0.00	*201.50 FL
8	1		*REVERSE SENSORS X SNN	0.00	0.00	*180.00 F
9	1		*REAR NO.PLATE WITH TRIM COVER X	0.00	0.00	*55.00 F
10	2		*REAR FENDER ADVERTISEMENT STICKER RH/LH / ACC	0.00	0.00	*200.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)

2,395.15

- List Item Discount on L Items (S\$)

392.03

Total Parts (S\$)

2,003.12

ComfortDelGro Engineering Pte Ltd/SHC2783A/18/05/2022 08:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Lim Tien Siong

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	400.00 ³⁵⁰
2	SPRAY PAINTING	New	300.00 ²⁵⁰
3	R/I REVERSE SENSORS	New	120.00 ⁴⁰
Gross Labour Cost (S\$)			820.00

ComfortDelGro Engineering Pte Ltd/SHC2783A/18/05/2022 08:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

2 Days.

P/P

before print plates.

Gao Ai q

18/5/22

v: 30pm.

1597.12

LK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for survey
- Parts purchase on a "best price" basis
- Third party repair on a "best price" basis
- No illegal work
- Supplier must be a registered company and is subject to the Insurance Company

Acknowledged by Repairer:

Signature:

Date: