

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 25 May 2022

Preliminary Advice

Insured Vehicle No	: GBG4429K	Accident Date	: 13/05/2022
TP Vehicle No	: SME8909X	Assignment Date	: 19/05/2022
Make	: HONDA VEZEL	Est. Duration of Repair	: 5
Date of Inspection	: 19/5/2022		
Inspection At	: PRIME AUTO CLAIMS SERVICE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,340.12
Revised Amount	:S\$	3,524.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,524.80
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	88,000.00
COE / PARF Rebate	:S\$	35,622.00
Salvage Value	:S\$	
Margin for Repair	:S\$	52,378.00

Remarks

- (X) The vehicle is economical for repair
- () The vehicle is not economical for repair
- (X) Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost .