

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	SURANCE (S) PTE LTD	Re	ef:	CS/CTI22004714/Aqy3	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909	Da	ate:	19/05/2022	
			Co	ode:	СТІ	
1. Policy Particulars :- THIRD PARTY (FOLLOW THROUGH INSPECTION)						
	Insured Veh.	SLM 3362A	Veh. Inspected		SKU 9247E	
	Policy No.	DMPCSNW00162702100	Coverage (\$)		0.00	
	Claim No.	SNM22D203317/C02	Excess (\$)		0.00	
	Assign From	ADELINE CHNG	Assign Date		19/05/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	Steering				
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
5. General Information						
	Accident Date	14/05/2022	Inspection Date		19/05/2022	
	Survey held at	t MODERN AUTOMOTIVE PTE LTD				
		BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					