



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22004724/Bvy3m4 Date: 05/10/2022	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SKZ 2663G	Veh. Inspected	SKF 4378Y
Policy No.		Coverage (\$)	0.00
Claim No.	C10015220/CD	Excess (\$)	0.00
Assign From	SHAFAWATI MD RABU	Assign Date	19/05/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA RAIZE 1.0X	c.c	996
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	A200A0160321	Colour	YELLOW
Odometer	1717 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65 R16	DUNLOP	6 mm
L/H Front Tyre	195/65 R16	DUNLOP	6 mm
R/H Rear Tyre	195/65 R16	DUNLOP	7 mm
L/H Rear Tyre	195/65 R16	DUNLOP	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	11/05/2022	Inspection Date	19/05/2022
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	