

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22004735/Any3e2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	17/08/2022	
			Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKR 3058P	Veh. Inspected	SMG 9332S	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10015334 /CD	Excess (\$)	0.00	
	Assign From	SHAFAWATI MD RABU	Assign Date	19/05/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA NOAH HYBRID	c.c	1797	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	ZWR800346153	Colour	WHITE	
	Odometer	302873 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/65 R15	HABILEAD	6 mm	
	L/H Front Tyre	205/65 R15	HABILEAD	6 mm	
	R/H Rear Tyre	205/65 R15	HABILEAD	6 mm	
	L/H Rear Tyre	205/65 R15	HABILEAD	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	18/05/2022	Inspection Date	20/05/2022	
	Survey held at	MG SOLUTION PTE LTD	•		
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: