

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT SOMPO INSURANCE SINGAPORE PL CS3/SMO22004737/Aty3e2 Ref: 50 RAFFLES PLACE #03-03 Date: 14/06/2022 SINGAPORE LAND TOWERSINGAPORE 048623 Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SKX 3316M** GBG 7603D Veh. Inspected Policy No. D21MTPV01015679 Coverage (\$) 0.00 Claim No. CMTD2201732/AGC Excess (\$) 0.00 MELVIN YE 19/05/2022 **Assign Date** Assign From **Vehicle Particulars & Condition** 2. **VOLKSWAGEN CADDY** Make & Model 1968 C.C HIDDEN 2017 Engine No. Year of Reg. WV1ZZZ2KZHX093675 **BLUE** Chassis No. Colour Odometer 66665 KM Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/65 R15 HANKOOK 6 mm 195/65 R15 HANKOOK L/H Front Tyre 6 mm 195/65 R15 HANKOOK R/H Rear Tyre 6 mm HANKOOK L/H Rear Tyre 195/65 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 19/05/2022 20/05/2022 (03:27 PM) Inspect Date / Time Accident Date **GARAGE 13 PTE LTD** Survey held at 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000

Report Ref No. CS3/SMO22004737/Aty3e2

Estimate Days of Repair

Inspected By

5b.

ADRIAN LING WAI PING

K.K.LAU CPT(RET)

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

ESTIMATED NORMAL PERIOD FOR REPAIR:

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

6 Working Days

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.