## **Shiau Chan (LKKAuto)**

From: Simon Ho (LKKAuto)

**Sent:** Friday, 20 May 2022 11:03 AM

**To:** Shiau Chan (LKKAuto)

**Subject:** Re: ASM-PAPER SURVEY SKN 2185H DONE BY STEVE (OUR REF:

CS3/ASM22000693/Eqy3-1)

Dear Shiau Chan,

Audit check done for SKN2185H, found no wheel alignment report for undercarriage parts replaced.

Best Regards,

## **Simon Ho**

## **LKK Auto Consultants Pte Ltd**

Phone: 6256-3561| email: <a href="mailto:simonho@lkkauto.com">simonho@lkkauto.com</a> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

The later langur secretic depayed. The fit may function record, record or older hindy the decision disconnection of the second or older hindy the decision for the second or older hindy the second or older hinds t

Save the Earth· Print only when necessary·

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Sent: Friday, 20 May 2022 9:30 am

To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>

Subject: ASM-PAPER SURVEY SKN 2185H DONE BY STEVE (OUR REF: CS3/ASM22000693/Eqy3-1)

Dear Simon,

For your audit.

Best Regards,

Shiau Chan (Ms) | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)