|   | CROUPSY/UVY3   |
|---|--|
| From: Date:   | Veh No: SL S 65-187 Yr Regn: 29 109/17                                       |
| Estimated Cost:   | Type: M.Car   M.Cycle   Bus   Van   Lorry   Taxi   Prime Mover               |
| OD / TP) WS / TP RES / OD RES / EVA / INV / MV                  | Truck / Trailer or   |
| To Inspect Vehicle No: SLS 6475 P                               | Make: Maxda 5- Wagon c.c 1998  |
| at Workshop m/s Nineteen  | Colour 3hy A/C: Insured / Std / NI / NA                                      |
| of  | Sp.Reading 89 / 86 T/Radio: Insured / Std / NI / NA                          |
| Insured: GSC 78486  | Eng/No:  |
| Policy No. DMCVSNA00108152104                                   | C/No: 2 JM6CW107/M0125944  |
| Claims No. SNM22D203387/C02                                     | Gen. Cond: Good + Fair / Poor / Burnt  |
| Sum Insured: Excess:  | Steering: Inorder / Jammed / Leaked / Burnt or                               |
| (Client's Record)   | Brake: Increar / Jammed / Leaked / Burnt or                                  |
| Make of Veh:  | Modi: Nil / S/Rim / STD A/Rim or   |
|   | Tyre Size: F: 205/53-R16   |
| (Policy Condition)  Remark: The veh had commenced its  N/S  O/S | R:   |
| repair at the time of inspection.                               | BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO YOKO OF |
| Bal. or Market Value: \$ 72/6                                   |  |
| IDAC Accident Rport: Consistent? : Yes or No                    | R/Bal. R/Bal. R/Bal. mm  |
| GIA / PR Seen: Consistent?: Yes or No                           | L/Bal. 6 mm L/Bal. 6 mm  |
| Est. Repairs: 6 days Res.: Yes or No                            | D.O.A. Clared 22 D.O.I. 20/5/23  |
| Lum Sum: 20 % 3 Val.: Yes or No                                 | Survey held at   |
| CA / REV / REP. / 24 HRS 7876                                   | Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or                  |
| Vehicle: IN / OUT   | Rear I new Wiscreen shottered  |
| Date: Person Contacted: L7A\$39372                              | The U/C / Chassis frame / Body Structure affected due to collision.          |
| Date / Time Action / Instruction                                |  |
| Vou a. A  |  |
| 16/22 45\$ 7600 informed te                                     | (red 16,045.35, 67%)   |
| 1000 monder ve  | renico   |
|   |  |
|   |  |
|   |  |
|   |  |
| Date/Time File Pass to?   | 0/0  |
| . Freii. Report   | ays Of Repair: 6   |
| : Final Report R  | esurvey No. of Trip: 2 Survey Fee:   |
| ) : Final Report R  | esurvey No. of Trip: 2 Survey Fee: Transportation:                           |
| Date/Time, File Return to?                                      | Survey No. of Trip: 2   Survey Fee:  |
| Date/Time, File Return to?                                      | esurvey No. of Trip: 2 Survey Fee: Transportation:                           |

TOTAL

## > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

| Vehicle Owner Particulars                     |                                       |  |
|---|---------------------------------------|--|
| Owner ID Type:                                | Singapore NRIC                        |  |
| Owner ID:                                     | 787B                                  |  |
| Vehicle Details                               |                                       |  |
| Vehicle No.:                                  | SLS6519P                              |  |
| Vehicle to be Exported:                       | No                                    |  |
| Intended Deregistration Date:                 | 20 May 2022                           |  |
| Vehicle Make:                                 | MAZDA                                 |  |
| Vehicle Model:                                | MAZDA5 WAGON 2.0 AT EU6               |  |
| Primary Colour:                               | Blue                                  |  |
| Manufacturing Year:                           | 2017                                  |  |
| Engine No.:                                   | PE10511443                            |  |
| Chassis No.:                                  | JM6CW1071H0125944                     |  |
| Maximum Power Output:                         | 111.0 kW (148 bhp)                    |  |
| Open Market Value:                            | \$17,372.00                           |  |
| Original Registration Date:                   | 29 Sep 2017                           |  |
| First Registration Date:                      | 29 Sep 2017                           |  |
| Transfer Count:                               | 0                                     |  |
| Actual ARF Paid: Intended PARF Rebate Details | \$17,372.00 & \$6                     |  |
| PARF Eligibility:                             | Yes                                   |  |
| PARF Eligibility Expiry Date:                 | 28 Sep 2027                           |  |
| PARF Rebate Amount:                           | \$13,029.00                           |  |
| Intended COE Rebate Details                   |                                       |  |
| COE Expiry Date:                              | 28 Sep 2027                           |  |
| COE Category:                                 | B - Car above 1600cc or 97kW (130bhp) |  |
| COE Period(Years):                            | 10                                    |  |
| QP Paid:                                      | \$49,189.00                           |  |
| COE Rebate Amount:                            | \$26,343.00                           |  |
| Total Rebate Amount:                          | \$39,372.00                           |  |
|   |                                       |  |

The information contained herein is correct as at 20 May 2022

ОК

## SGCARMART.COM Login Sign up Articles Resources **Used Cars** Rental Cars Sell My Car Directory **Products** Insurance Forum **New Cars** youbiz The best corporate card with unlimited cashback and real 0% FX fees Land Rover Discovery Sport 2.0A 7-Seater At \$109,800. $\mathbf{G}$ Post an Advertisement HIN LUNG AUTO Sell it yourself! Advertise it at just Promotions! 1 Owner, Fully Agent Maintained! Very Low \$68 until it's SOLD! One Stop Car Hub Mileage! Finance, Insurance, Workshop New and Used Cars Automobile Gallery StarAd Ways of Selling Advertiser Login Post an Ad Sort by Date Posted V 20 V results/page Advanced Search 14 vehicles Search Mazda 5 Any Category Reg Date Veh Type Status Make Model Price Depreciation Eng Cap Mileage Search Selection Mazda 5 Anv Any 2017 Anv Anv Any Available Mazda 5 2.0A \$74,800 \$12,230 /yr 16-Oct-2017 1.998 cc 61.643 km MPV Available 1 year extended warranty by SgCarmart premium dealer with official warranty certificate, lowest depreciation, high loan available, free s... This car comes with 6-mth sgCarMart Warranty - the best protection for your car. Learn More CARWAY Posted: 19-May-2022 MPV Available 26-May-2017 1.998 cc 85,000 km Mazda 5 2.0A Sunroof \$73,800 \$12,760 /vr Cheapest in the market. Accident free with beautiful paint and sheltered parked daily. Clean and beautiful non smoker interior. Twin DOW. This car comes with 6-mth sgCarMart Warranty - the best protection for your car. Learn More Posted: 19-May-2022 \$70,800 \$12.880 /vr 15-Feb-2017 1.998 cc 65.916 km MPV Available Mazda 5 2.0A Sunroof HIGH SPECS 7 SEATER MPV IN TOP NOTCH CONDITION THAT LOOK LIKE NEW UNIT! DUAL POWERED SLIDING DOORS, EXTREMELY. Car (S) Pte Ltd Posted: 18-May-2022 \$12,600 /yr 1,998 cc 86,001 km MPV Available Mazda 5 2.0A \$75,800 14-Sep-2017 1 owner unit, beautiful grey paint work, one of the best seller in the market, spacious 7 seater MPV w dual sliding door for easy access... Car Empire Automobiles Pte Ltd Posted: 18-May-2022 2016 Mazda 3 1.5A Duluxe (PHV Private Hire Rental) \$385/week GRAB - Excellent exterior styling Mazda 3 (2016) with good fuel economy & a comfortable interior for PHV Rental. More info about this vehicle Available \$78,800 \$13,340 /vr 21-Aug-2017 1.998 cc 82,000 km MPV Mazda 5 2.0A 1 owner unit with meticulous condition inside out, genuine & authentic low mileage done, fuel efficient & practical MPV with dual power... Hua Yang Credit Pte Ltd Posted: 16-May-2022 Mazda 5 2.0A \$79,800 \$12,840 /yr 05-Dec-2017 1,998 cc 55,600 km MPV Available 1 Owner Unit. Low Mileage done. Fully serviced at agent. Most popular 7 seater in the market. Very huge space with sliding doors for a l...

1Y Auto Pte Ltd

Posted: 15-May-2022

## **NINETEEN AUTOWERKS PTE LTD**

Blk 436 Tampines Street 43 #07-97 Singapore 520436

Tel: (65) 9674 1991

 $oxed{\boxtimes}$  nineteenautowerks@gmail.com

## **ESTIMATE**

20/5/22 20/5/22 2/5 4 7600/



DATE:

DOA:

A:

**VEHICLE NO:** 

MAKE & MODEL:

20-May-22 18-May-22 SLS 6519 P

MAZDA 5 WAGON

| DESCRIPTION                     |            | QUANTITY | AMOUNT     | TOTAL                      |              |
|---------------------------------|------------|----------|------------|----------------------------|--------------|
| LIST ITEMS                      |            |          |            |                            |              |
| Tailgate 300                    | ner<br>ner | 1        | \$1,871.10 | 1637                       | \$1,871.10   |
| Tailgate logo                   | ner        | 1        | \$99.00    | St                         | \$99.00      |
| Tailgate emblem "Mazda"         | 111        | 1        | \$98.00    | 42                         | \$98.00      |
| Tailgate emblem "5"             | ner        | 1        | \$76.00    | 38                         | \$76.00      |
| Tailgate emblem "Skyactive"     | ner        | 1        | \$48.00    |                            | \$48.00      |
| Tailgate weatherstrip           | tul        | 1        | \$295.00   | 162-60                     | \$295.00     |
| Tailgate inner lock             | COL        | 1        | \$475.00   | 162-60                     | \$475.00     |
| Tailgate lock sensor            | 11         | 1        | \$395.00   | _ 10 10                    | \$395.00 ×   |
| Tailgate outer garnish          | cre        | 1        | \$175.00   |                            | \$175.00     |
| Tailgate number plate lamp (set | 11         | 1        | \$210.00   |                            | \$210.00 🗶   |
| Tailgate damper                 | 17         | 2        | \$195.00   |                            | \$390.00 ×   |
| Tailgate trimboard              | se (cre    | 1        | \$452.00   | 421.60                     | \$452.00     |
| Tailgate reflector lamp         | one        | 2        | \$356.00   |                            | \$712.00     |
| Taillamps                       | cne        | / 2      | \$687.00   |                            | \$1,374.00   |
| Tailgate windscreen             | Shatter    | 1        | \$1,158.00 | 1121.00                    | \$1,158.00   |
| Tailgate windscreen moulding    | res        | 1        | \$224.00   | 126.10                     | \$224.00     |
| Tailgate wiper                  | ms         | 1        | \$80.00    |                            | \$80.00 🗶    |
| Tailgate wiper motor            | In         | 1        | \$356.00   |                            | \$356.00     |
| Rear bumper                     | 20         | 1        | \$986.00   | 915.40                     | \$986.00     |
| Rear bumper side retainer       | suf        | 2        | \$68.00    |                            | \$136.00     |
| Rear bumper bracket             | NS         | 2        | \$48.00    |                            | \$96.00 🗴    |
| Rear bumper reinforcement       | But        | 1        | \$385.00   | 191-00                     | \$385.00     |
| Rear bumper under cover         | 11         | 1        | \$120.00   |                            | \$120.00 ×   |
| Rear bumper reflector           | nn         | 2        | \$87.20    |                            | \$174.40 >   |
| Rear end panel                  | 20/1enf    | 1        | \$580.00   | 491.70                     | \$580.00     |
| Rear end panel top garnish      | 121        | 1        | \$249.00   | 491.20<br>181.20<br>384.00 | \$249.00     |
| Spare tyre panel                | R          | 1        | \$1,088.00 |                            | \$1,088.00 🗶 |
| Spare tyre panel cover tray     | en         | 1        | \$427.00   | 385.00                     | \$427.00     |
| Exhaust muffler                 | np         | 1        | \$993.00   |                            | \$993.00 X   |
| Exhaust mounting                | 10         | 4        | \$48.00    |                            | \$192.00     |
| Exhaust heat shield             | 11         | 1        | \$171.00   |                            | \$171.00 ×   |
| Side body panel                 | 17         | 2        | \$1,126.80 |                            | \$2,253.60 🗴 |
| Side body panel inner trim      | 17         | 2        | \$748.00   |                            | \$1,496.00 > |
| Side body panel inner shield    | 17         | 2        | \$294.00   |                            | \$588.00 >   |
| Side body panel glass moulding  | 1          | 2        | \$177.20   |                            | \$354.40 X   |
| Roof Spoiler                    | 11         | 1        | \$374.00   |                            | \$374.00     |
|                                 |            |          | Total      | 600                        | \$19,151.50  |

102

| *  |           | Less 10% 20% |        | \$1,915.15           |
|--|-----------|--------------|--------|----------------------|
|  |           |              |        | \$17,236.35          |
| SPECIAL NETT ITEMS                             |           |              |        |                      |
| Sundries                                       | 1         | \$60.00      | 17     | \$60.00 🗴            |
| MSMA Tailgate sealant                          | 1         | \$100.00     | ner    | \$100.00 4           |
| Tailgate inner trim clips (set)                | 1 Sef     | \$45.00      | nu     | \$45.00              |
| Tailgate outer garnish clips (set)             | 1         | \$30.00      | 11     | \$30.00 x            |
| Tailgate reflector lamp seal                   | 2         | \$30.00      | 11     | \$60.00              |
| Tailgate reflector lamp clips (set)            | 2         | \$25.00      | 11     | \$50.00              |
| Taillamp seal                                  | 2         | \$40.00      | 11     | \$80.00              |
| Taillamp clips (set)                           | 2         | \$35.00      | 17     | \$70.00 >            |
| Rear bumper clips (set)                        | 1 504     | \$80.00      | ner    | \$80.00              |
| Rear end panel sealant                         | 1         | \$80.00      | nec    | \$80.00              |
| Rear end panel top garnish clips (set)         | 1         | \$40.00      | 11     | \$40.00              |
| Spare tyre panel sealant                       | 1         | \$70.00      | 17     | \$70.00              |
| Side body panel sealant                        | 2         | \$80.00      | 11     | \$160.00             |
| Side body panel inner trim clips (set)         | 2         | \$55.00      | 11     | \$110.00             |
| Side body panel inner shield clips (set)       | 2         | \$32.00      | 17     | \$64.00 X            |
| Reverse sensor with module                     | 1 set     | \$300.00     | Shetel | \$300.00 2           |
| In car camera                                  | 1         | \$350.00     | Su     | \$350.00 🗶           |
|  |           |              |        | \$1,749.00           |
|  | Parts Tot | tal          |        | \$18,985.35          |
| LABOUR CHARGES                                 |           |              |        |                      |
| Panel beating                                  |           |              | 800    | \$2,000.00           |
| Spray Painting                                 |           |              | 1000   | \$1,800.00           |
| Check wiring system after disconnect & connect |           |              | 1003   | \$80.00              |
| Remove & refit interior upholstery             |           |              | 75     | \$200.00             |
| Remove & refit tailgate component              |           |              | 80     | \$100.00             |
| Remove & refit exhaust pipe                    |           |              | 11 X   | **CONTRACTOR NO. CO. |
| Remove & refit reverse sensor and check        |           |              | Sv     | \$100.00             |
| To apply undercoating for rust roofing         |           |              | 60     | \$200.00             |
|  | Labour T  | otal         |        | \$4,660.00           |
| Total Parts and Labour Cost of Repair          |           | -            |        | ¢22 645 25           |
| rotar raits and tabout cost of hepan           |           |              |        | \$23,645.35          |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: