



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

STRIDES AUTOMOTIVE SERVICES PTE LTD
60 WOODLANDS INDUSTRIAL PARK
E4SINGAPORE 757705

Ref: CS3/SMR22004763/Eqy3e2

Date: 08/06/2022

Code: SMR

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHC 4897S	Veh. Inspected	SMZ 5307S
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/05/22/2036	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	20/05/2022

2. Vehicle Particulars & Condition


Make & Model	TOYOTA VIOS	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	MR2B23F3001220828	Colour	BLACK
Odometer	56025 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	DUNLOP	4 mm
L/H Front Tyre	185/60 R15	DUNLOP	4 mm
R/H Rear Tyre	185/60 R15	DUNLOP	4 mm
L/H Rear Tyre	185/60 R15	DUNLOP	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.



5. General Information

Accident Date	13/05/2022	Inspect Date / Time	20/05/2022 (02:42 PM)
Survey held at	CAR LABORATORIES PTE LTD NO. 1 BUKIT BATOK CRESCENT #04-56 WCEGA PLAZA SINGAPORE 658064		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
- D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
--	-----------------------

Report Ref No. CS3/SMR22004763/Eqy3e2

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.