

GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

GREEN FOREST LANDSCAPE PTE LTD

8 KAKI BUKIT AVE 4

05-25 PREMIER @ KB

Singapore 415875

24th MAY 2022

Accident date: 17th MAY 2022

Estimated repair cost for vehicle no: SLM9779S HONDA CIVIC

TP ALK.

Xiao Tony

MR HF C5650GT002878

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$1,120.00 687.
2	1	Rear boot lid emble logo <i>new</i>		\$75.00 45
3	3	Rear boot lid emble logo clips <i>new</i>	\$6.50	\$19.50 10.
4	1	Rear Boot Lid Civic logo <i>3 new</i>		\$45.00 ✓
5	1	Rear boot lid vtec logo		\$40.00 ✓
6	2	Rear Boot Lid side reflector <i>the new</i>	\$312.00	\$624.00 x
7	1	Rear boot lid inner rubber <i>at</i>		\$255.00 119.
8	1	Rear Boot Lid Number Plate <i>3 new</i>		\$50.00 x
9	1	Rear Boot Lid Inner Trim board		\$485.00 x
10	2	Rear tail lamp <i>the new</i>	\$415.00	\$830.00 x
11	1	Rear end panel <i>Repair</i>		\$455.00 +
12	1	Rear End Panel Top Garnish <i>Defend</i>		\$214.00 ✓
13	2	rear bumper inner retainer <i>the new</i>	\$132.00	\$264.00 x
14	1	Rear Bumper <i>Defend</i>		\$862.40 630.
15	2	Rear Bumper Side Bracket <i>new</i>	\$115.20	\$230.40 50.
16	1	Rear Bumper reverse sensor <i>Dented</i>		\$350.00 240.
17	10	Rear bumper clips <i>new</i>	\$6.50	\$65.00 30.
18	1	Rear Bumper center lower cover <i>Defend</i>		\$385.00 280.
19	1	Rear bumper reinforcement <i>Dented</i>		\$448.00 246
20	2	Rear Bumper side reflector <i>3 new</i>	\$98.20	\$196.40 x
21	2	rear bumper side reflector chrome <i>3 new</i>	\$105.20	\$210.40 x
22	2	Rear Exhaust chome pipe	\$0.00	\$320.00 x.

2676

Subtotal :- \$7,544.10

Labour charges

To Remove & refix cushion

~~\$120.00~~ 40.

To remove & Refix rear Windscreen

~~\$120.00~~ x

To Remove & refix reverse Sensor

~~\$120.00~~ 50

Gum

~~\$50.00~~ x

Tuff kote

~~\$120.00~~ 40

To Check Wiring System

~~\$60.00~~ 30

Panel beating

~~\$800.00~~ 500

Spray painting

~~\$800.00~~ 600.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :- \$2,190.00

Total:- \$9,734.10

total: 34008

W/S: 2.7K

04 Days