

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date 1 Nov 2020

DATE: 13.05.2022

LKK-

MODEL: Hyundai Ioniq

INSURANCE: CHINA TAIPING C/P/P

VEHICLE NO.: SHD4953H

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper X NN ✓ BR	1		\$ 459.40
	Rear Bumper Reinforcement X NN	1		\$ 394.80
	Rear Bumper Reinforcement Bracket LH/RH X NN	2	\$ 138.10	\$ 276.20
	Rear Bumper Centre Moulding ee	1		\$ 451.25
	Rear Bumper Lower Centre Moulding X NN	1		\$ 155.00
	Rear Bumper Cover Clips X ec	10	\$ 2.20	\$ 22.00
	Rear Bumper Tow Cover X NN	1		\$ 98.80
	Rear Bumper Reflector LH / RH X NN	2	\$ 41.15	\$ 82.90
	Rear Foglamp X NN	1		\$ 201.50
	SUB TOTAL			\$ 2,141.85 932.65
	LESS 20% DISCOUNTED TOTAL			\$ 428.37 746.12
	Reverse Sensors X NN	1		\$ 180.00
	Rear No. Plate With Trim Cover / C/A	1		\$ 55.00
	NETT TOTAL			\$ 235.00
	SPARE PARTS TOTAL			\$ 1,948.48
	Labour Charge			
	Panel Beating		\$ 400.00	
	Spray Painting Charge		\$ 300.00	
	Remove/Refix Reverse Sensor		\$ 120.00	
	TOTAL LABOUR		\$ 820.00	
	ESTIMATE TOTAL		\$ 2,768.48 1491.12	

350
250
40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Days.
P/P
before part photos
& After part photos
Gino Qiang
13/5/22
4pm

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before any spray painting
- To display damaged parts for survey
- Part replacement on "like for like" basis
- Not to be held liable for "no-nibble" basis
- Not to be held liable for "no-nibble" basis

Head and
The Company