

NIK

AM 600
AM 600

Company Reg No: 201929175W

Contacts: _____

No.	Description of spare parts	Qty	Amount \$S
1	Tailgate 1720	1	\$ 2,379.00
2	Tailgate "Harrier" emblem	1	\$ 76.00
3	Tailgate "Turbo" emblem	1	\$ 79.00
4	Tailgate reverse camera	1	\$ 954.00
5	Tailgate RH side rubber sensor	1	\$ 732.00
6	Tailgate LH side rubber sensor	1	\$ 732.00
7	Tailgate windscreen glass rubber moulding RH	1	\$ 101.00
8	Tailgate windscreen glass rubber moulding LH	1	\$ 101.00
9	Tailgate windscreen glass rubber moulding lower	1	\$ 67.00
10	Tailgate outer garnish	1	\$ 1,302.00
11	Tailgate outer garnish centre emblem	1	\$ 67.00
12	Tailgate RH lamp assy	1	\$ 505.00
13	Tailgate LH lamp assy	1	\$ 505.00
14	Tailgate mechanism lock with cover	1	\$ 975.00
15	Tailgate weatherstrip	1	\$ 447.00
16	Tailgate inner trim board	1	\$ 578.00
17	Tailgate inner trim board clips	1set	\$ 60.00
18	RH taillamp assy	1	\$ 575.00
19	RH taillamp lower bracket	1	\$ 86.00
20	LH taillamp assy	1	\$ 575.00
21	LH taillamp lower bracket	1	\$ 86.00
22	Rear fender RH inner trim board	1	\$ 545.00
23	Rear fender RH inner trim board clips	1set	\$ 30.00 60.00
24	Rear fender LH inner trim board	1	\$ 545.00
25	Rear fender LH inner trim board clips	1set	\$ 30.00 60.00
26	Rear bumper 742	1	\$ 905.00
27	Rear bumper clips	1set	\$ 30.00 60.00
28	Rear bumper RH side retainer	1	\$ 87.00
29	Rear bumper LH side retainer	1	\$ 87.00
30	Rear bumper RH reflector	1	\$ 67.00
31	Rear bumper RH reflector LH	1	\$ 67.00
32	Rear bumper lower spoiler	1	\$ 489.00
33	Rear bumper inner sponge	1	\$ 124.00
34	Rear bumper RH side reverse sensor	1	\$ 482.00
35	Rear bumper RH centre reverse sensor	1	\$ 482.00
36	Rear bumper LH centre reverse sensor	1	\$ 482.00
37	Rear bumper LH side reverse sensor	1	\$ 482.00

Set Fender
\$835 ←

38	Rear bumper reverse sensor holders	4	\$	88.00	
39	Rear bumper reverse sensor retainers	4	\$	68.00	
40	End panel	1	\$	1,006.40	
41	End panel inner garnish	1	\$	447.00	
42	End panel inner garnish clips	1set	\$	30.00 40.00	
43	End panel antenna sensor	1	\$	176.00	
44	Rear compartment panel top inner board	1	\$	885.00	
45	Rear compartment panel RH side tool tray	1	\$	178.00	
46	Rear compartment panel LH side tool tray	1	\$	178.00	
47	Rear compartment panel top sponge	1	\$	339.00	
48	Rear compartment panel top board	1	\$	668.00	
49	Exhaust silencer	1	\$	703.00	
50	Exhaust silencer gasket	1	\$	45.00	

Parts less 25% \$ 20,827.40
 Total \$ 5,206.85
 Total \$ 15,620.55

No.	Special Nett Items		Amount S\$
1	Tailgate windscreen glass sealant	1	\$ 40.00 70.00
2	Tailgate windscreen glass inner seal	1	\$ 30.00 50.00
3	End panel joint sealant	1	\$ 30.00 80.00
Total:			\$ 200.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 800.00 1,600.00
2	Spray painting on affected areas and panels	\$ 600.00 1,400.00
3	Check wiring and lighting system on affected areas	\$ -80.00
4	Apply rust coating chemical on affected areas and panels	\$ 100.00
5	Remove and reinstall tailgate windscreen glass to assist repair	\$ 120.00 240.00
6	Remove and reinstall tailgate reverse camera to assist repair	\$ 120.00
7	Remove and replace tailgate inner components to assist repair	\$ 80.00 120.00
8	Remove and replace rear bumper reverse sensors to assist repair	\$ 0.00 100.00
9	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 280.00
10	Remove and replace exhaust silencer and gasket to assist repair	\$ 180.00

Agreed Amount: _____ (Part by Part / Lump sum) Total: \$ 4,220.00

Working days: _____

Spare Parts: \$ 15,620.55

Special Nett: \$ 200.00

Labour: \$ 4,220.00

Total Amount: \$ 20,040.55

Survey & Resurvey

23/5/2022

TG4m Am

Lump sum repair

Repair days 8

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repaker

Signature:

Date: