

KV

Not Authorized
 11 Sep @ 1900h
 Recovery After Paint
 4 days

FBH4530U

Accident along PIE (Changi) Slip road towards Kallwang Way

S/N	Qty	Description	(S\$)		
Parts					
1	1pcs	Front Mudguard	\$	Sm	75.00 X
2	1pcs	Front Wheel	\$	Sm	350.00 X
3	1pcs	Front Wheel Shaft	\$	By	130.00 7
4	1pcs	Front Wheel Bearing	\$	me	80.00 7
5	1pcs	Front Disc Rotor	\$	Sm	200.00 X
6	2pcs	Front Fork Assy LH & RH @240	\$	MT	480.00 7
7	1pcs	Stem Steering	\$	By	165.00 7
8	1pcs	Handlebar	\$	Me	80.00 7
9	1pcs	Clutch Lever	\$	MT	40.00 7
10	1pcs	Brake Lever	\$	Sm	40.00 X
11	2pcs	Balancer @25/pcs	\$	MT	50.00 7
12	2pcs	Side Mirror @30/pcs	\$	MT	60.00 7
13	1pcs	Front Headlamp Cover	\$	CM	60.00 7
14	2pcs	Front Signal Lamp @25/pcs	\$	MT	50.00 X
15	1pcs	Headlight Assy	\$	Me	160.00 7
16	1pcs	Front Mask	\$	Sm	90.00 X
17	1pcs	Front Mask Base	\$	CM	120.00 7
18	1pcs	Pilot Light	\$	Sm	250.00 7
19	1pcs	Belly shield covering	\$	Sm	90.00 7
20	1pcs	Front Side Fairing LH	\$	CM	95.00 7
21	1pcs	Front Side Fairing RH	\$	Sm	95.00 X
22	1pcs	Rear Side Fairing LH	\$	CM	95.00 7
23	1pcs	Rear Side Fairing RH	\$	Sm	95.00 X
24	1pcs	Centre covering	\$	CM	120.00 7
25	1pcs	Front Footrest Bar	\$	MT	75.00 7
26	2pcs	Front Footrest Rubber @45/pcs	\$	Sm	90.00 X
27	1pcs	Gear Padal	\$	MT	50.00 7
28	1pcs	Rear LH Foot Rest	\$	By	45.00 7
29	1pcs	Rear LH Foot Rest Bracket	\$	MT	80.00 7
30	1pcs	Exhaut pipe	\$	Me	400.00 X
			Total	\$	3,810.00
			-10%	\$	381.00
			Parts Sub Total	\$	3,429.00
Special Nett					
32	1pcs	Front fork seal	\$	Me	80.00 3012
33	1pcs	Front fork oil	\$	Me	300.00 3012
34	1pcs	IU Unit	\$	Me	160.00 7
35	1pcs	No. plate (front)	\$	Sm	20.00 X
36	1set	Body sticker	\$	Me	180.00 7

Labour		Total	\$	740.00	
1	Towing				
2	To realign body frame		\$	100.00	300
3	To R&R fornt suspension, handle bar, headlamp, side fairing, and attachments.		\$	350.00	1000
			\$	400.00	1300
Labour Total:		\$		850.00	
Sub Total (labour and parts):		\$		5,019.00	

Vehicle is at 5 Soon Lee Street #01-02 Pioneer Piont S(627607)
Please arrange your surveyor to come down to survey the vehicle.
Contact : Daryl 98356259

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: